

N. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p align="center"><small>DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE THAT LOCATION FOR PERMIT FORM C-101 FOR SUCH PROPOSALS.</small></p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil &amp; Gas Lease No.</p>
<p>6. Unit Agreement Name</p>		
<p>7. Farm or Lease Name HCW Exploration, Inc.</p>		<p>8. Well No. 4</p>
<p>9. Address of Operator P.O. Box 10585, Midland, TX 79702</p>		<p>10. Field and Pool, or Wildcat Jalmat</p>
<p>11. Location of Well UNIT LETTER <u>I</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>23 S</u> RANGE <u>36 E</u> N.M.P.M.</p>		
<p>13. Elevation (Show whether DF, RT, GR, etc.) 3381.5' RT</p>		<p>12. County Lea</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:                      SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

14. Describe in brief the Proposed or Completed Operations. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. SEE RULE 1103.

Proposed P&A operations as follows:

Set CIBP @ 2898' (10' above 4½" liner). Perforate 5½" csg @ 350', set cmt retainer at 300' & cmt w/100 sxs Class "C" w/2% CaCl to circulate cmt to surface.  
Set 5 sx cmt plug at surface. Clean & level location per Commission rules.  
We do not plan to pull any pipe from this well.

TD @ 3550'. 5½" csg set & cmt @ 2970' w/400 sx Reg. Trinity. 8-5/8" csg set & cmt @ 304' w/150 sx Trinity. Cmt was circulated to surface.

\*\*\*100' plug @top of salt approx. 1200'  
Load hole w/10# salt gel  
10 sx. surface plug

OPERATOR MUST BE NOTIFIED  
72 HOURS PRIOR TO COMMENCING WORK

15. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Steve Douglas</u> Steve Douglas	TITLE <u>Operations Manager</u>	DATE <u>9-21-84</u>
APPROVED BY <u>Eddie W. Seay</u>	TITLE <u>Oil Conservation</u>	DATE <u>SEP 24 1984</u>
CONDITIONS OF APPROVAL, IF ANY:		

\*\*\*SEE ABOVE