

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Salt Water Disposal</b>	7. Unit Agreement Name
2. Name of Operator <b>Albert Gackle</b>	8. Farm or Lease Name <b>George Etz</b>
3. Address of Operator <b>Box 2038, Hobbs, New Mexico 88240</b>	9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>N</b> <b>330</b> FEET FROM THE <b>South</b> LINE AND <b>1650</b> FEET FROM THE <b>West</b> LINE, SECTION <b>27</b> TOWNSHIP <b>23 South</b> RANGE <b>36 East</b> NMPM.	10. Field and Pool, or Wildcat <b>Jalmat</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
☒

OTHER **Salt Water Disposal Well**

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was drilled in 1949. Surface casing was set at 1235' and cement was circulated. Was plugged and abandoned the same year after tests were made.

After Commission Order #3221 became effective, application was made to re-enter this well to complete as a salt water disposal well. Cement plugs were drilled and cleaned out to 3620'. Plugged back from 3620' w/pea gravel to 3368', and from 3368' to 3358' w/Cal-Seal. 5" 18# Exline casing was set at 3357' and cemented w/730 sacks cement. Circulated back to 1000'; cement plug was drilled out and well was cleaned out to 3620'. Formation was treated w/2000 gallons of acid. 2-7/8" plastic lined tubing was run w/packer set at 3327'.

Well was connected to water disposal tank and is taking water on vacuum.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Albert Gackle TITLE Operator DATE 3-18-1969

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: