

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator: GULF OIL CORPORATION	8. Farm or Lease Name Manda (NCT-C)
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> <u>580</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>35</u> TOWNSHIP <u>23S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Langlie-Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3338' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> P&A Jalmat Gas zone & produce Langlie-Mattix as single	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3625' TD. POH w/tbg. Set RBP, 1 jt tbg & treating pkr @ 3400' & cap RBP w/10' sd. Squeeze Jalmat perms w/150 sx Class "C" cmt + .2% HLX-249 & .8% Halad-9. Test to 500 psi. Wash fill f/top of pkr. Mill out & recover pkr.

Run conventional down hole production equipment & put well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. B. Sikes, Jr. TITLE Area Engineer DATE 11-13-79

APPROVED BY Orig. Signed by Jerry Sexton TITLE \_\_\_\_\_ DATE NOV 15 1979

CONDITIONS OF APPROVAL, Dist. Supv.