Orig. Signed by Jerry Sexton

GONDITIONS OF APPRODICE LE SUPE

OIL CONSERVATION DIVISION

we. or cories Acce	OIL CONSERVATION DIVISION	
DISTRIBUTIO	P. O. BOX 2088	Form C-103
SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78
FILE	4-NMOCD-Hobbs 1-WLG	5a, Indicate Type of Lease
U.S.G.S.		StateXX Fee
LAND OFFICE	1-File 1-JDM-Engr.	
OPERATOR	11-WIO's 1-BWI-Foreman	5, State Otl & Gas Lease No.
<u> </u>	1-BB	B-243
	SUNDRY NOTICES AND REPORTS ON WELLS	
HT BEU TOH OO!	IS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
	USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
1.	GAS	
well X	WELL OTHER-	Myers Langlie Mattix Un
2. Name of Operator		8. Farm or Lease Nume
Getty O	oil Company	Myers Langlie Mattix Un
3. Address of Operator		9. Well No.
	. 720 Wahba Naw Marrian 99240	
P.O. BO	x 730 Hobbs, New Mexico 88240	104
4. Location of Well		10. Field and Pool, or Wildcat
	P 660 FEET FROM THE SOUTH LINE AND 660 FEET FROM	Langlie Mattix
UNIT LETTER	T COO FEET FROM THE DOGGE LINE AND DOGG PEET FROM	mmmmmm,
THE East	LINE, SECTION 36 TOWNSHIP 23S MANGE 36E NMPM.	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3328' DF	Lea ()
: 16:		
	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	ner Data
	OTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WOR	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
_		· · · · · · · · · · · · · · · · · · ·
TEMPORARILY ABAHDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDOMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	:
	other clean out and fr	ac X
OTHER	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
17. Describe Proposed	or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE !		
11 (01 (01 - 6	16 0/1 G	dell or por galler
	ulf Oil Co. squeezed Jalmat perforations; drilled out & tes	sted. OK. POH. Getty
re	sumed workover after Gulf completed P&A of Jalmat zone.	
11/20/81 Pi	cked up & ran Clustrite shoe. Tagged @ 3430'. Cleaned ou	t to 3495'. POH w/tbg
&	tools. Shoe worn out. Pieces of tbg in wash pipe. Top o	of fish @ 3575'.
	in bit & tagged @ 3495' and cleaned out to 3608' (T.D.).	
	in bit a tagged & 3433 and citathed out to 3000 (1.b.).	*
11/24/81		
to		•
12/1/81 D ri	lled new hole & cleaned out from 3608' to 3706'.	
12/2/81 Sc	chlumberger ran BHC Sonic log 2650-3695'.	
	th pkr @3338'. Western fraced open hole @ 3389'-3706' w/3	3.000 gals Apollo Cross-
	inked gel, 39,000#, 10-20 sand, 18,000#, 8-12 sand, 3000 ga	_
sa	alt w/2 blocks max press. 3000#, min press 1200#, ISIP 1000)#, and in 15 min 800%
Ra	ate 16 BPM. Total load 963 bbls.	
12/7/81 Ra	n 106 jts (3352') 2 7/8" tbg. Set at 3363'. SN @ 3332'.	Ran 2 1/2 x 1 1/2 x 20'
	mp. Rigged down. Pumping and testing.	· -, · · · ·
-	-	
12/22/01 PC	DB 24 hrs 12 x 64, 20 BO, 262 BW.	
	•	
18 I hereby cartifu that	the information above is true and complete to the best of my knowledge and belief.	
10. I hereby centry the		
/1/2	-11/1/1/1/10 / 1. Nove	
NIGHED XIG	WI R WILL Area Superintendent	DATE 1/27/82
Male	Crockett	