Office	Energy, Minerals and N	Mexico		Form C-1	
District I	Energy, witherars and N	iaturai Resources	WELL API NO.	Revised March 25, 1	999
1625 N. French Dr., Hobbs, NM 872^C District II	OIL CONSERVATI	ION DIVISION	30-0	₂₅ . ૦ ૧૫ છપ્	
811 South First, Artesia, NM 87210 District III	2040 South I		5. Indicate Type of	f Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NN		STATE 🔀	FEE 🗆	
District IV 2040 South Pacheco, Santa Fe, NM 87505			6. State Oil & Gas 8910138170 -	Lease No.	
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROP	CES AND REPORTS ON V	VELLS FN OR PLUG BACK TO A	1	Unit Agreement Name:	
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	ICATION FOR PERMIT" (FORM C	C-101) FOR SUCH	Myers Langlie Ma	attix Unit	
1. Type of Well: Oil Well Gas Well	Other Injection	04			
2. Name of Operator			8. Well No.	(
OXY USA WTP Limited Partner 3. Address of Operator	snip	192463	9. Pool name or W		\dashv
P.O. Box 50250 Midland, TX	79710-0250		Langlie Mattix 7		4
4. Well Location Unit Letter	2310 feet from the 50	suff line and 1	feet from	n the west lir	
Section 36	Township 73	Range 34	NMPM	County Lea	
Section 9 4	10. Elevation (Show wheth		***************************************	County Lea	
11. Check	Appropriate Box to Indicate	ate _l Nature of Notice,	Report, or Other	Data	
NOTICE OF INT	** *	1	SEQUENT REF		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI	NG OPNS.	PLUG AND ABANDONMENT	
	MULTIPLE [☐ CASING TEST AND		7.07.1.10 G14.11.2144	
PULL OR ALTER CASING L	COMPLETION	CEMENT JOB	ل		
OTHER:	COMPLETION	CEMENT JOB OTHER: MIT - TA		cluding estimated date	_[X
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests t	completion Ed Operations (Clearly state all SEE RULE 1103. For Multip	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach	ve pertinent dates, in wellbore diagram of future use.		_[X
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation.	completion Ed Operations (Clearly state all SEE RULE 1103. For Multip	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach	ve pertinent dates, in wellbore diagram of		_[X
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests t	completion ed Operations (Clearly state al SEE RULE 1103. For Multiple to temporarily abandon the Perfs-3444	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach ais well for possible -3676 Pkr/CII	ve pertinent dates, in wellbore diagram of future use.		_[X
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3740' PBTD-37	completion ed Operations (Clearly state all SEE RULE 1103. For Multip to temporarily abandon the Perfs-3444 sing integrity test 24hr controlled to the control of the c	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach ais well for possible -3676 Pkr/CII	ve pertinent dates, in wellbore diagram of future use. BP- <u>3333</u>		_[X
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3740' PBTD-3740' PBT	completion ed Operations (Clearly state al SEE RULE 1103. For Multiple to temporarily abandon the Perfs-3444 sing integrity test 24hr or circulate well with min. This Approximate Approximate and the Completion of the Complet	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach ris well for possible -3676 Pkr/CII es in advance. treated water, pressival of Temporary	ve pertinent dates, in wellbore diagram of future use. BP- <u>3333</u>		_[X
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3740' PBTD-3740' PBT	completion ed Operations (Clearly state all SEE RULE 1103. For Multiple to temporarily abandon the sing integrity test 24hr is ing integrity test 24hr in in.	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach ris well for possible -3676 Pkr/CII es in advance. treated water, pressival of Temporary	ve pertinent dates, in wellbore diagram of future use. BP- <u>3339</u>		_[]
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to TD-3740' PBTD-3740' PBT	completion ed Operations (Clearly state al SEE RULE 1103. For Multiple to temporarily abandon the same of the sam	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach This well for possible The possible of the possible o	ve pertinent dates, in wellbore diagram of future use. BP-3333		_[X
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. 0XY USA WTP LP requests to TD-3740' PBTD-3740' PBT	completion ed Operations (Clearly state al SEE RULE 1103. For Multiple to temporarily abandon the Perfs-3444 sing integrity test 24hr circulate well with min. This Approximate to the best	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach This well for possible The possible of the possible o	ve pertinent dates, in wellbore diagram of future use. BP-3339 ure test casing		_[X
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. 0XY USA WTP LP requests to TD-3740 PBTD-37 1. Notify BLM/NMOCD of cate of the proposed work). 1. Notify BLM/NMOCD of cate of the proposed work). Of the period of the period work work and the proposed work). Of the period work work work work work work work work	ed Operations (Clearly state all SEE RULE 1103. For Multiple to temporarily abandon the Perfs-3444 esing integrity test 24hr e. circulate well with min. This Approx Abandonment	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach ris well for possible -3676 Pkr/CII es in advance. treated water, pressival of Temporary t Expires of my knowledge and belief TLE Sr. Regulatory A	ve pertinent dates, in wellbore diagram of future use. BP-3333 ure test casing Analyst D Telephore	Proposed completion ATE Z 25 03 ne No. 915-685-5717	_[]
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. 0XY USA WTP LP requests to TD-3740 PBTD-37 1. Notify BLM/NMOCD of cate of the proposed work). 1. Notify BLM/NMOCD of cate of the proposed work). Of the period of the period work work and the proposed work). Of the period work work work work work work work work	ed Operations (Clearly state all SEE RULE 1103. For Multiple to temporarily abandon the Perfs-3444 esing integrity test 24hr e. circulate well with min. This Approx Abandonment	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach ris well for possible -3676 Pkr/CII es in advance. treated water, pressival of Temporary t Expires of my knowledge and belief TLE Sr. Regulatory A	ve pertinent dates, in wellbore diagram of future use. BP-3333 ure test casing Analyst D Telephore	Proposed completion ATE Z 25 03 ne No. 915-685-5717	_ [X
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. OXY USA WTP LP requests to the starting any proposed work). OXY USA WTP LP requests to the starting part of the starting part	ed Operations (Clearly state all SEE RULE 1103. For Multiple to temporarily abandon the Perfs-3444 esing integrity test 24hr e. circulate well with min. This Approx Abandonment	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach ris well for possible -3676 Pkr/CII es in advance. treated water, pressival of Temporary t Expires of my knowledge and belief TLE Sr. Regulatory A	ve pertinent dates, in wellbore diagram of future use. BP-3333 ure test casing Analyst D Telephore	Proposed completion ATE Z 25 03 ne No. 915-685-5717	
OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. 0XY USA WTP LP requests to TD-3740 PBTD-37 1. Notify BLM/NMOCD of cate of the proposed work). 1. Notify BLM/NMOCD of cate of the proposed work). Of the period of the period work work and the proposed work). Of the period work work work work work work work work	completion ed Operations (Clearly state al SEE RULE 1103. For Multiple to temporarily abandon the Perfs-3444 sing integrity test 24hr circulate well with min. This Approximate to the best	OTHER: MIT - TA Ill pertinent details, and gi ple Completions: Attach ris well for possible -3676 Pkr/CII es in advance. treated water, pressival of Temporary t Expires of my knowledge and belief TLE Sr. Regulatory A	ve pertinent dates, in wellbore diagram of future use. BP-3333 ure test casing Analyst D Telephore	Proposed completion ATE Z 25 03 ne No. 915-685-5717	

