CONSERVATION COMMISSION



Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

	indicate nature	or report by	cnecking perov	7.		
REPORT ON BEGINNING DRILLING OPERA- TIONS REPORT ON RESULT OF SHOOTING OR CHEM- ICAL TREATMENT OF WELL			REPORT ON REPAIRING WELL REPORT ON PULLING OR OTHERWISE ALTERING CASING			
REPORT ON RESULT OF PL	UGGING OF WELL					
		June 22 .	1949	Hob	bs. Now	Mixt.ee
OIL CONSERVATION COMM SANTA FE, NEW MEXICO Gentlemen:	ISSION,	Ďa			Place	
Following is a report on the wo	rk done and the result		der the headin		1	
Company or			Lease	Well No		in the
C SW NW	of Sec2		248	, R. 561	!	N. M. P. M.,
Langlie-Mattix	Field,			Lea		County.
The dates of this work were as	follows: June	20, 1949 a	June 22,	1949		-
/20/49. Coment was all b water came in, in or	e hour. Picked		pipe & dri	lling was r	e sume d	intendent
William Dy	Name		Company			Title
Subscribed and sworn befor		is true	y swear or af and correct	firm that the in	ormation	given above
			n Distric	t Superinte	indent	
	Notary Public		enting CL11	on Service ompany or Oper	Oil Gom	0 8137
My commission expires Ma	rch 18, 1951	Addres	Drawer (, Hobbs, No	w Mexic)
Remarks:	· PPOUFED			Roy 4	unkra	(II) h

APPROVED

JUN 2 4 1949

y we will be a second $\lim_{t\to\infty} \lim_{t\to\infty} \frac{1}{t} = \lim_{t\to\infty} \frac{1}{t} \int_{\mathbb{R}^n} |\nabla f(t)|^2 dt = \lim_{t\to\infty} \frac{1}{t} \int_{\mathbb{R}^n} |\nabla f(t)|^2 dt = 0$

they form with the