

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO	30 025 09505
5. Indicate Type of Lease	STATE FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	EUGENE COATS
8. Well No.	
9. Pool Name or Wildcat	JALMAT TANSILL YATES SEVEN RIVERS

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS"	
1. Type of Well	OIL WELL ☒ GAS WELL OTHER
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter O 660 Feet From The SOUTH Line and 1980 Feet From The EAST Line Section 3 Township 24S Range 36E NMPM LEA COUNTY 10 Elevation (Show whether DF, RKB, RT, GR, etc.) 3392' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☒ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐ PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐ OTHER: RECOMPLETE IN TANSILL YATES ☒	SUBSEQUENT REPORT OF:
--	-------------------------------------

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-05-01: MIRU, NDWH, NUBOP, TIH W/BIT & CSG SCRAPER ON WS.
 2-06-01: TIH TO 3300'. HUNG UP 3300-3260-WORK LOOSE. TIH W/PKR ON TBG. SET PKR @ 3240' & 2800'-OK. REL PKR TIH W/GR/CNL/CBL & LOG 3265-2200'. TIH W/CIBP & SET @ 3240'. TIH W/CMT BAILER & DUMP 35' ON TOP OF CIBP. NEW PSTD-3205'. LOAD CSG FROM SURF. TIH W/PKR & SET 30'. LOAD & TEST CIBP & CHART TO 500# FOR 30 MINS - LOST 25#-OK. REL PKR.
 2-07-01: TIH W/PERF GUN & PERF 2975-79,2984-89,2994-99,3046-68,3080-3102,3109-13,3130-45. PERF2908-12,2926-58,2962-63. TIH W/PKR. & SN ON FRAC TBG TEST TO 8000#. SET PKR @ 2814'. TEST BACKSIDE TO 500#-OK. ACIDIZE JALMAT PERFS 2908-3145, W/5000 GALS 15% NEFE HCL.
 2-08-01: REL PKR & LOWER THRU PERFS TO 3105'. PULL UP & RESET PKR @ 2782'. PRESS BACKSIDE TO 900#. FRAC JALMAT PERFS 2908-3145 W/54 156 GALS 30# X-LINKED GEL 60 QUAL C02. FLOW ON 24/64-30/64 CHOKE FOR 16 HRS.
 2-09-01: KILL WELL W/40 BBLS 2% KCL WTR. REL PKR. TIH W/WS. TIH W/PKR, SN & TBG. STOP PKR @ 950'.
 2-10-01: KILL WELL W/90 BBLS 2% KCL WTR. TIH W/92 JTS 2 3/8" TBG. NDBOP. NUWH. PUMP 50 BBLS PKR FLUID DN BACKSIDE. SET PKR @ 2847' W/26,000# TENSION. COULD NOT TEST CSG & PKR. PUMP 35 BBLS DN BACKSIDE. INSTL GATE VALVE W/PMPNG TEE. RU SWAB. FL @ 400'.
 2-12-01: KILL W/20 BBLS 2% KCL WTR. NDWH, NUBOP. REL PKR. TIH W/KNOTCHED COLLAR, BAILER ON TBG. TAG @ 3050. C/O FRAC SAND TO 3221'. TIH W/SAME TOOLS. TAG @ 3160'. LOST 60' IN 1 HR. C/O TO 3220'. PULL UP TO 1900'.
 2-13-01: KILL W/40 BBLS 2% KCL WTR. TAG DN @ 3181. BAIL OUT SAND FR 3181-3232. TIH & TAG SAND @ 3195'. BAIL OUT TO 3240'. PULL UP TO 1900'.
 2-14-01: TAG FILL @ 3210. C/O FRAC SAND TO 3240.
 2-15-01: TIH W/PKR SET @ 2847'. RU SWAB. FL @ 400. END FL @ 700'. SWABBING. REL PKR. TIH W/SN OPEN ENDED ON TBG. TAG @ 3230.
 2-22-01: TIH W/TBG. TAC, SN @ 3126. TAC @ 2844. REM BOP. FLANGE UP WH. TIH W/PMP. & RDS. RIG DOWN. UNSET PMP. NDWH. NUBOP. TAG FILL @ 3231. TIH W/PKR & SN ON TBG. PULL PKR TOL 1500'.
 3-12-01: TIH W/CIBP ON TBG SET @ 3218'. TIH W/PKR. SN. PKR @ 3215. PRESS TEST CIBP TO 520#. TEST FOR 30 MINS. PULL TO 2844 & SET. RU SWAB. KILL W/30 BBLS 2% KCL WTR. UNSET PKR. TIH W/TBG. SN, TAC. SN @ 3125. TBG @ 3157. TAC @ 2840. NDBOP. NUWH. SET TAC. TIH W/PMP & RDS. RIG DOWN. SHUT IN - UNECONOMICAL. 3-22-01: ON 24 HR OPT. PUMPED 0 BO, 125 BW. & 0 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 4/17/01

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE