

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Argus Production Company	8. Farm or Lease Name E.C. Mosley
3. Address of Operator 2902 Republic Bank Tower, Dallas, Texas 75201	9. Well No. 2
4. Location of Well UNIT LETTER P 335 660 FEET FROM THE South LINE AND 1650 FEET FROM East LINE, SECTION 10 TOWNSHIP 24-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Jalmat
15. Elevation (Show whether DF, RT, GR, etc.) 3392 DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Propose to move in workover rig about September 23, 1970.
2. Set cast iron bridge plug above present perforations 3590' to 3620'.
3. Perforate, acidize and test from 3578' to 3513'.

The purpose of this workover is to reduce the water production and increase oil production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>by Glenda Swain</u>	TITLE <u>Secretary-Treasurer</u>	DATE <u>9/16/70</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT 1</u>	DATE <u>SEP 21 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

SEP 18 1970

OIL CONSERVATION COMM.
HOBBS, N. M.