State of New Mexico Submit 3 Copies To Appropriate District Form C-103 Office Energy, Minerals and Natural Resources Revised March 25, 1999 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 District II 30-025-09547 OIL CONSERVATION DIVISION 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III 1000 Rio Brazos Rd., Aztec, NM 87410 STATE Santa Fe, NM 87505 FEE x District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Myers Langlie Mattix Unit 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator 8. Well No. OXY USA WIP Limited Partnership 192463 242 3. Address of Operator 9. Pool name or Wildcat Langlie Mattix 7 Rvr-QN-GB P.O. Box 50250 Midland, TX 79710-0250 4. Well Location Unit Letter ___ 1980 feet from the south 660 line and feet from the line Section Township 24S Range **NMPM** County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION **CEMENT JOB** OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. NOTIFY NMOCD OF INTENT TO P&A 11/23/00. MIRU PU 11/24/00, RDWH, NU BOP. RIH & STORY CIBP @ 3400 (DEPTH CHG APPR BY BUDDY W/ NMOCD). CIRC HOLE W/ 9.5#MLF, SPOT 25sx CMT, WOC/ORTH & TAG @ 3296', POOH TO 2965', SPOT 60sx CMT, POOH, WOC. RIH & TAG @ 2633', POOH TO 1254', SPOT 25sx CMT, POOH, WOC. RIH & TAG @ 1100', RIH & PERF @ 350', RIH & SET CICR @ 183', SQZ 40sx PT, POOR, WOC. RIH & TAG @ 183', PRESSURE TEST SQZ TO 500#, OK, SPOT 30sx CMT FROM 183' TO STRFACE (RDPU 11/28/00. DUG OUT CELLAR, CUT OFF WH & ANCHORS, INSTALL DRY HOLE MARKER, CLEAN LOCATION WELL PEA'D I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE_ TITLE Sr. Regulatory Analyst Type or print name David Stewart Telephone No. 915-685-5717 (This space for State use

APPROVED BY

Conditions of approval, if any: