


PLUGGING & ABANDONMENT WORKSHEET

(2 STRING CSNG)

OPERATOR TEXACO Exploration & Production
LEASENAME Cooper JAL UNIT

SECT 13 TWN 24-S RNG 36 E
FROM 330 N/S/L 2310 EWL
TD: 3550 FORMATION @ TD Langhite
PBDT: FORMATION @ PBDT



	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	8 5/8	280	SURF	Circ	
INTMED 1					
INTMED 2					
PROD	5 1/2	3438	1900	CALC	
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
CUT & PULL @			TOP - BOTTOM		
INTMED 1			PERFS	-	
INTMED 2			OPENHOLE	-	
PROD					

*REQUIRED PLUGS DISTRICT I

RUSTLER (ANYD)	
YATES	
QUEEN	
GRAYBURG	
SAN ANDRES	
CAPTAN REEF	
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BRUSHY CANYON	
BONE SPRING	
GLORIETA	
BLINEBRY	
TUBB	
DRINKARD	
ABO	
WC	
PENN	
STRAWN	
ATOKA	
MORROW	
MISS	
DEVONIAN	

PLUG	TYPE	SACKS	DEPTH
PLUG	PLUG	CMNT	
EXAMPLES			
PLUG #1	OH	35 SXS	6400'
PLUG #2	SHOE	50 SXS	5350'-5450'
PLUG #3	CIBP/35'		4800'
PLUG #3	CIBP	25 SXS	4800'
PLUG #4	STUB	50 SXS	3600'-3700'
PLUG #5	RETNR SQZ	200 SXS	400'
PLUG #6	SURF	10 SXS	0-10'
PLUG #1	CIBP	25 SX	3400-3200
PLUG #2	B-SALT	30 SX	3000-2700
PLUG #3	T-SALT	25 SX	1300-1100
PLUG #4	8 5/8	75 SX	350-200
PLUG #5	SURF	10 SX	10-SURF
PLUG #6			
PLUG #7			
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #			
PLUG #			

YATES

TD 3550