

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR MERIDIAN OIL INC		8. FARM OR LEASE NAME MYERS B	
3. ADDRESS OF OPERATOR P.O. Box 51810, Midland, TX 79710-1810		3a. AREA CODE & PHONE NO. (915)688-6943	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface F, 2310' FNL & 1650' FWL		9. WELL NO. 1	
		10. FIELD AND POOL, OR WILDCAT LANGLIE MATTIX 7R QN GRBG	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC 13, T24S, R36E	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3317' GR	
		12. COUNTY OR PARISH LEA	
		13. STATE NM	

### 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

NOTIFY BLM PRIOR TO COMMENCING PLUGGING OPERATIONS.

SPOT 50' CMT PLUG ON TOP OF CMT RETAINER @ 3465-3515'. USE 5 SXS CLASS "C" CMT. CIRC HOLE W/ GELLED 9 PPG BRINE.

SPOT CMT PLUG ACROSS CASING SHOE, LINER TOP & BASE OF SALT @ 2580 TO 3015'. USE 55 SXS OF CLASS "C" CMT. MAKE A CASING SCRAPER RUN TO 1250'.

PERFORATE 4 SQUEEZE HOLES @ 1335'. SET CMT RETAINER @ +/-1215'. SQUEEZE CMT TOP OF SALT SECTION UNDER RETAINER W/ 40 SXS CLASS "C" CMT. SPOT 10 SXS CMT ON RETAINER.

PERFORATE 4 SQUEEZE HOLES @ 257'. SET CMT RETAINER @ +/-575'. SQUEEZE CASING LEAK AND ANNULAR AREA ACROSS SURFACE CASING SHOE W/ 95 SXS CMT. SET CMT PLUG FROM 575' TO SURFACE (USE 100 SXS CMT).

CUT OFF CASING 3' BELOW GROUND LEVEL AND INSTALL P&A MONUMENT. CLEAR AND RESTORE LOCATION.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Kerann Scholz*

TITLE

PRODUCTION ASST

DATE

03/30/92

(This space for Federal or State office use)

APPROVED BY

*David H. Glass*

TITLE

DATE

4/3/92

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

**MERIDIAN OIL**  
 MYERS B NO. 1  
 LANGLEIE MATTIX FIELD  
 LEA COUNTY, NEW MEXICO

KLM 1/17/92

