•			
NO. OF COPIES RECEIVED	يۇد. بۇرۇ	\$	Form C-103
DISTRIBUTION			Supersedes Old
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State Fee. X
OPERATOR			5. State Oil & Gas Lease No.
			B 152436
SUNDI DO NOT USE THIS FORM FOR PR USE MAPPLICA	RY NOTICES AND REPORTS ON OPOSALS TO DRILL OR TO DEEPON ON PLUG PTION FOR PERMIT	WELLS BACK TO A DIFFERENT RESERVOIR.	
1.		·	7. Unit Agreement Name
OIL A GAS WELL			
2. Name of Operator	8. Farm or Lease Name		
Worldwide Energy	J. L Isbell		
3. Address of Operator 1700 Broadway - 1600 Tower Building, Denver, Colo. 80290			9. Well No.
) #4		
4. Location of Well	10. Field and Pool, or Wildcat		
UNIT LETTER B	660 FEET FROM THE North	LINE AND 1980 FEET FR	Jalmat
THE <u>East</u> LINE, SECTI	ION 15 700 NSHIP24S	RANGE 36E NMP	
	12. County		
ÖINNINNINNINNIN	<u>3382'D.F.</u>	s	Lea ())))))
16. Check	Appropriate Box To Indicate N	lature of Notice, Report or C	ther Data
NOTICE OF 1	NTENTION TO:	•	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	PLUG AND ABANDONMENT		
PULL OR ALTER CASING			
		OTHER	
OTHER			
17 Describe Bronosed or Completed O	perations (Clearly state all pertinent det		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1 103.

•

See attached list.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Darry C. Muff	TITLE	Production Engineer	DATE_	7/15/80)
APPROVED BY_ Eddi Seam	TITLE	OIL & GAS MENTON	DATE		(19)
CONDITIONS OF APPROVAL, IF ANY:					

J. L. ISBELL #4

- 1. 1/17/78 Spotted 35 sacks of cement from 3167' to 2975'.
- 1/18/78 Displaced hole with 130 barrels of 9.5 pounds per gallon mud. Cut 7" casing at free point (1640').
- 3. 1/19/78 Pulled 56 joints of 7" casing. Spotted 40 sacks of cement at 1689'.
- 1/20/78 Tagged top of cement plug at 1566'. Spotted 90 sacks of cement at 1450'.
- 5. 1/21/78 Cement went out into formation. Pumped in 2 sacks cottonseed hulls and 45 sacks of cement with 80# Quickseal.
- 6. 1/23/78 Top of cement at 1420'. Pumped in 2 sacks of cottonseed hulls and 75 sacks of cement with 60# of Quickseal.
- 7. 1/24/78 Top of cement at 1345'. Spotted 90 sacks of cement.
- 8. 1/25/78 Top of cement at 1203'. Set 10 sacks cement plug at surface.
- 9. 2/3/78 Welded steel plate on top of 9-5/8" surface casing.

٠,

•