UNITED STATES SUBMIT IN TRIPLICATE.

Form approved. Budget Bureau No. 42-R1424.

May 1963)	DEPARTMENT THE INTERIOR (Other Instruc-	5. LEASE DESIGNATION AND SERIAL NO.
(Do not v	SUNDRY NOTICES AND REPORTS ON WELLS use this form for proposals to drill or to deepen or plug back to a different reseuse "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALGOTTEE OR TRIBE NAME
1.	GAS (77)	7. UNIT AGREEMENT NAME
WELL		8. FARM OR LEASE NAME
	Energy Corporation	R. L. Gates A-23
3. ADIRESS OF O		9. WELL NO.
Suite 1100,	, 718 - 17th Street, Denver, Colorado 80202	1 10. FIELD AND POOL, OR WILDCAT
4. LOCATION OF V See also space	WELL (Report location clearly and in accordance with any State requirements.* e 17 below.)	
At surface		Jalmat 11. SEC., T., R., M., OR BLK. AND
Contor of)	NW/4 of NW/4 of Sec. 23, T24S, R36E	SURVEY OR AREA
Lenter of f	1W/4 OF NW/4 OF Sec. 25, 1245, RJOE	Sec. 23, T24S, R36E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
_	3329 GL - 3341+ KB (original)	Lea New Mexico
 16.	Check Appropriate Box To Indicate Nature of Notice, I	Report or Other Data
19.		SUBSEQUENT REPORT OF:
	NOTICE OF (NIENTION TO:	
TEST WATER	(
FRACTURE TI		1 1 1
SHOOT OR AC	(Othor)	ACIDIZING A
REPAIR WELL	(Norge:	Report results of multiple completion on Well on or Recompletion Report and Log form.)
(Other)	OPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give powork. If well is directionally drilled, give subsurface locations and measured a	ortinent dates, including estimated date of starting any
proposed to thi	work. If well is directionally drilled, give subsurface locations and measured a is work.)*	nd true vertical deptas for an markers and zones perti-
11/26/76	Rigged up. Rigged up reverse unit, killed we Wouldn't come. Pulled 30,000#. Rigged down Rigged up. Pulled and laid down Guiberson pamissing. Picked up Baker mill and ran on 100 down for night at 5:30 P.M.	to reset sills under derrick legs. cker - 2 out of 4 belly springs O' of 2-7/8" work string. Shut
11/27/76	Ran remainder of work string (total 2188'). Picked up 2-7/8" tubing out of derrick to make up remainder of work string. Ran mill to 3217' (B.P. at 3273' = 56' of fill). Cleaned out 7' of FeS scale fill. Mill apparently rotating on belly springs left in hole. Clean out going very slowly. Pulled out of hole with tubing. SDFN at 5:30 P.M.	
11/28/76	Attempted to thaw out air lines on rig for 3 hours with no success. Added glyco to air system. Shut down for remainder of day.	
11/29/76	Fished 2 - 4" pieces of spring. Ran mill on 6 - 3-1/2" drill collars, 26# per foot to top of fill. Cleaned out down to top of bridge plug at 3273'. Milling on bridge plug. SDFN at 5:30 P.M.	
11/30/76	Thawed out rig and flow line. Tried to get of apparently frozen. Milling on bridge plug we coming back through tubing; apparently pressured (Continued on attachment.) Titly that the foregoing is true and correct	ith no circulation. Water started
-		nineer
SIGNED	J.N.Dull TITLE Production Eng.	
	OBY TITLE	D FOR RECORD
CONDITION	NS OF APPROVAL, IF ANY:	1977 0/10

*See Instructions on Reverse Side OCICAL SURVEY
U. S. GEOLOGICAL MEXICO
U. S. GEOLOGICAL MEXICO

Instructions

eral and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Fedlocal, area, or regional procedures and practives, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Consult local Item 4: If there are no applicable State requirements, locations on Pederal or Indian land should be described in accordance with Federal requirements. State or Federal office for specific instructions.

In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not scaled off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

47 - 48

