

NEW MEXICO STATE LAND OF. E
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr. C. G. Staley State Of _____, N. Mex., Dec. 9th 1928
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon State A" Well
No. I in 990 ft. fr. S line 330 ft. fr. E Sec. 23 of Sec. _____, T. 26, R. 36,
N. M. P. M., Jal. Oil Field, Lee County.
We plan to commence work on December 13th, 19 28.

The reasons for wishing to abandon the well are as follows:

**Encountered sulphur
water at 3474 ft.**

The present condition of the well is as follows:

The work which we propose to do in abandoning the well is as follows:

**Bridged hole
at 3450 drive 600 lbs. of lead wool and lead plug with taper
mandrel, 15 bag of cement then pump hole full of heavy mud.**

Approved 12/26 1928 Sincerely yours,
Cranfill, And Reynolds.
Company or Operator.

Except as follows:

By A. L. Reynolds
Position Supt.

Send communications regarding this well to

Name Cranfill And Reynolds.

Address Box. 685 Wink, Texas.

A. L. Staley
State Geologist or Oil and Gas Inspector.