

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 South First, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

1220 South St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

FORM C-103  
Revised March 25, 1999

**OIL CONSERVATION DIVISION**  
1220 South St. Francis Drive  
Santa Fe, NM 87505

WELL APINO. 30-025-10599
5. Indicate Type of Lease <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Skelly Penrose A Unit
8. Well No. 40
9. Pool name or Wildcat Langlie-Mattix; 7Rivers-Queen-Grayburg

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER Injection Well	
2. Name of Operator Apache Corporation	
3. Address of Operator 2000 Post Oak Blvd., Ste. 100, Houston, Texas 77056-4400	
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>3</u> Township <u>23S</u> Range <u>37E</u> NMPM <u>Lea</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3284'</u> GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
<input type="checkbox"/> Perform Remedial Work	<input type="checkbox"/> Remedial Work
<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Altering Casing
<input type="checkbox"/> Temporarily Abandon	<input type="checkbox"/> Commence Drilling Operations
<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandonment
<input type="checkbox"/> Pull or Alter Casing	<input type="checkbox"/> Casing Test and Cement Job
<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Other Request TA Status

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Apache requests approval of Temporary Abandoned status for the Skelly Penrose A Unit # 40 well.


1/18/01 CIBP set @ 3265' (original packer depth) per verbal permission of E L Gonzalez - NM/OCD  
2/12/01 Performed Casing Integrity Test @ 565# for 30 minutes - OK. Test witnessed by Buddy Hill - NM/OCD  
See attached chart

This wellbore will be evaluated for utilization in continued unit development.

This Approval of Temporary  
Abandonment Expires 2/21/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE <u>Debra J. Anderson</u>	TITLE <u>Sr. Engineering Technician</u> DATE <u>2/15/01</u>
TYPE OR PRINT NAME <u>Debra J. Anderson</u>	TELEPHONE NO. <u>713-296-6338</u>
(This space for State Use)	
APPROVED BY <u>GARY WINK</u>	TITLE <u>FIELD REP. II</u> DATE <u>2/21/06</u>

CONDITIONS OF APPROVAL, IF ANY:



CALIBRATED  
CHARTS  
SATAVIA, N.Y.

Apache Corp.

SPA'UT.  
#40


P-3-23-37

2-12-01

MI-PD-1000-8-96MIN

B.H.

30 MIN.



Rate  
10000  
96 MIN  
Last Gt. 2-12-01  
Amer. Mtr.