| | class "C" with 10# sand and 2% CaCl. Mixed and pumped at 1 1/2 BPM at 1500#- |
|---------|--|
| | 2300# pressure. SD and dropped plug. Displaced cmt to 229' with 5 1/2 bbls |
| | water at $1/2 - 0$ BPM. TP went from 2300# to 2500#. |
| 7/8/82 | Waiting on cmt 44 hrs. |
| 7/9/82 | Tagged plug at 107' (came up hole 118'). Run bit to 1100'. No cmt. TOH |
| | w/ tbg and bit. Halliburton attempted to squeeze. Couldn't establish |
| | enough rate (2500 $\#$ at 1/4 BPM w/ H ₂ O). |
| 7/12/82 | Ran 4 3/4" bit, drlg plug @ 3225'. Pull bit - prepare to frac. |
| 7/13/82 | Ran 118 jts (3648') 2 7/8" tbg open end at 3654'. Western spotted 500 |
| | gals 30% acid, 3660-3552, perfs 3552-30. Pull tbg. Ran Howco pkr, set @ |
| | 3434'. Treated perfs 3530-52 + open hole 3553-3660 w/ 39,000 gals 2% KCL, |
| | 69,000# 12-20 sand, 3000# salt, 3 staged, max 2800#, min 2000#, ISIP 1900# |
| | rate 20 BPM. 15 min 1700#, load 1122 bbls. Placed well back on production. |
| | |
| | |
| | |

. . . .