

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
-----	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER. Plugged & Abandoned		7. Unit Agreement Name Skelly Penrose "B" Unit
2. Name of Operator Skelly Oil Company		8. Farm or Lease Name Skelly Penrose "B" Unit
3. Address of Operator P. O. Box 1351, Midland, Texas 79701		9. Well No. 50
4. Location of Well UNIT LETTER <u>H</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>23S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Langlie-Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3320' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Moved in workover rig April 27, 1975.
- Set 12 sack cement plug 3358-3458'.
- Shot off 5-1/2" OD casing at 1474' and pulled 45 jts.
- Cemented down 8-5/8" OD casing with 150 sacks Class C cement with 3/4# unibeads per sack, 2% CaCl and 150 sacks Class C neat cement 2% CaCl and 100 sacks Class H cement, displaced to 900'. Well back flowed cement to cellar.
- Loaded hole with 500 gals. SAF-MARK III.
- Set 185 sack cement plug 220-1480'.
- Set 2 sack cement plug surface-60'.
- Installed dry hole marker.

Well plugged and abandoned May 4, 1975.

All intervals not cemented or otherwise filled were filled with 10.2# mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(Signed) J. R. Avent J. R. Avent TITLE Dist. Admin. Coordinator DATE May 20, 1975

APPROVED BY *John W. Runyan* TITLE DATE 5/20/1975

CONDITIONS OF APPROVAL, IF ANY: