

UPDATE 11-29-01
CURRENT COMPLETION

[illegible]

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-10.
Revised March 25, 1996

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-10692
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 685270
7. Lease Name or Unit Agreement Name: Skelly Penrose 'A' Unit
8. Well No. 46
9. Pool name or Wildcat Langlie Mattix 7-Rv Queen
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3298' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Injection Well	2. Name of Operator Prize Operating Company
3. Address of Operator 3500 William D. Tate, Suite 200, Grapevine, Texas 76051	4. Well Location Unit Letter B : 660 feet from the North line and 1980 feet from the East line Section 9 Township 23S Range 37E NMPM County Lea
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Prize Operating Company respectfully requests approval to Temporarily Abandon the well by the following procedures as prescribed by the Oil Conservation Division.

1. MIRU service unit and pull out of hole with tubing and packer.
2. RIH with CIBP and set at approximately 3450'. (current perfs 3484-3624')
3. Test CIBP and casing to 500 psi.
4. RD and move off wellbore. Leave well TA'd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Don Aldridge TITLE Regulatory Analyst DATE 12-6-2001

Type or print name Don Aldridge Telephone No. 817-424-0454

(This space for State use)

APPROVED BY _____ TITLE NATURAL RESOURCES DATE 12-6-2001
Conditions of approval, if any: