

OIL CONSERVATION

P. O. BOX 2038

SANTA FE, NEW MEXICO 87501

Form O-100
Revised 10-1-73

1. Indicate Type of Lease	
State ☐	Fee ☒
2. State Oil & Gas Lease No.	

SUMMARY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM O-101) FOR SUCH PROPOSALS.

☒ GAS WELL ☐ OTHER		7. Unit Agreement Name SKELLY PENROSE A UNIT
8. Operator TEXACO PRODUCING INC.		8. Farm or Lease Name
9. Address of Operator P.O. Box 728, Hobbs, N.M. 88240		9. Well No. 51
10. Location of Well LETTER <u>G</u> 1980 FEET FROM THE <u>North</u> LINE AND 1980 FEET FROM <u>East</u> LINE, SECTION <u>10</u> TOWNSHIP <u>23S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat LANGLIE MATTIX
11. Elevation (Show whether DF, RT, GR, etc.)		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

☐ REMEDIAL WORK ☐ INITIALLY ABANDON ☐ ALTER CASING ☐ PLUG AND ABANDON ☐ CHANGE PLANS ☐	☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPER. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER <u>Repaired water flow</u>	☐ ALTERING CASING ☐ PLUG AND ABANDONMENT ☐
---	---	---

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations.) SEE RULE 1103.

1. Rigged up. TOH w/production equipment.
2. Set 7" CIBP at 3200', perfed 2 sqz holes at 1225'.
3. Set 7" cmt ret. at 1105'. Sqzd. perfs at 1225' w/175 sx cl "H". Pld. out of cmt. ret.
4. Sqzd. 7" csg. perfs at 1225' w/1000 gal Flochek, 200 sx cl "H" and 3% CaCl. Over displ. w/20 bbls. P/20 bbls. 10% CaCl wtr., 1000 gal Flochek and 200 sx cl "H" w/5# GIL, 10% Calsel, 1/4# Flochek, 6 1/2# ST and 3# SD. Over displ. w/20 bbls. pld out of ret and revers out 20 bbls.
5. Sqzd. 7" csg. w/600 gal Flochek, 100 sx cl "H" w/5# GIL, 10# Calsel, 1/4# Flochek, 6 1/2# ST and 3# Sp/sx.
6. Ran CBL from 1100' to surf.
7. Perfed at 596' w/2 JS. POH w/pkr. P/300 sx cmt and additives.
8. DOC to 612'.
9. P/500 sx cl "H" w/3% CaCl.
10. P/125 sx cl "H" w/3% CaCl.
11. DOC to top of ret at 1105'. DOC and ret 1225'.
12. Tagged CIBP at 3140' and drld out. C/O to 3625' TD.
13. TOH w/production equipment., test and place on production.

SEP 24 1985

RECEIVED
SEP 23 1985
CCTD OFFICE
HOEBS OFFICE