

Submit 3 Copies to Appropriate District  
Office

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 South First, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

1220 South St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

**OIL CONSERVATION DIVISION**

1220 South St. Francis Drive  
Santa Fe, NM 87505

FORM C-103  
Revised March 25, 1999

WELL API NO. 30-025-10703	
5. Indicate Type of Lease <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Skelly Penrose A Unit	
8. Well No. 44	
9. Pool name or Wildcat Langlie-Mattix; 7Rivers-Queen-Grayburg	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
☐ OIL WELL ☐ GAS WELL ☒ OTHER Injection Well

2. Name of Operator  
Apache Corporation

3. Address of Operator  
2000 Post Oak Blvd., Ste. 100, Houston, Texas 77056-4400

4. Well Location  
Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line  
Section 10 Township 23S Range 37E NMPM Lea County  
10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3288' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
<input type="checkbox"/> Perform Remedial Work	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Remedial Work	<input type="checkbox"/> Altering Casing
<input type="checkbox"/> Temporarily Abandon	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Commence Drilling Operations	<input type="checkbox"/> Plug and Abandonment
<input type="checkbox"/> Pull or Alter Casing		<input type="checkbox"/> Casing Test and Cement Job	
<input type="checkbox"/> Other		<input type="checkbox"/> Other	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1.) Set cement retainer @ 3500'. Cement squeeze perforations 3516' - 3618' w/ 75 sx. Cap cement retainer w/ 35' cement. Tag top of cement
- 2.) Spot cement plug @ 3225' - 3325' w/ 55 sx. Tag top of plug.
- 3.) Spot cement plug @ 2150' - 2250' w/ 55 sx. Tag top of plug.
- 4.) Spot cement plug @ 1075' - 1225' w/ 100 sx. Tag top of plug.
- 5.) Spot cement plug @ 50' to surface w/ 35 sx.
- 6.) Install P&A marker.

THE COMMISSION MUST BE NOTIFIED 24  
HOURS BEFORE THE BEGINNING OF  
ANY NEW OPERATIONS FOR THE CHOO  
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debra J. Anderson TITLE Sr. Engineering Technician DATE 2/5/01

TYPE OR PRINT NAME Debra J. Anderson TELEPHONE NO. 713-296-6338

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: