State of New Mexico

Submit 3 Copies Form C-103 Energy, Minerals and Natural Resources Department to Appropriate District Office Revised 1-1-89 OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM \$8240 P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE STATE DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 6. State Oil & Gas Lease No. 0141096 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: Cline - Federal GAS T OTHER Convert To SWD WELL 2. Name of Operator 8. Well No. Grace Petroleum Corporation 9. Pool name or Wildcat 3. Address of Operator Langlie - Mattix 6501 N. Broadway Ext., Oklahoma City, OK 73116 Well Location 1653 1650 South West Feet From The Unit Letter Feet From The 232 37E Lea 15 **NMPM** Section Township Range County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3B06 - DF Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING** TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** Convert to SWD Well BWd-362 OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4/25/89 POOH with Rods and tbg; GIH with packer and set @ 2600'; test packer and annulus to 600 psi for 5 mins. - ok; POOH with packer; 4/26/89 GIH with nickle plated Uni PKR VI and set at 2600'; test annulus to 600 psi for 10 mins - ok; POOH

4/27/89 Unload 90 Jts of 2 3/8" fiberglass tbg.

4/28/89 GIH with on-off tool; seat on-off tool on packer @ 2600'; test annulus to 300 psi for 25 mins. (Oil Commission okayed test)

4/29/89 Tie to water tanks; begin injection; well on vacuum.

	RIGINAL SIGNED BY JURRY SEXTON		A = 5
I I I L OK I KO'I I KNOWL	Mike Pavelka		TELEPHONE NO.
SIONATURE	Miketawala	Op. Eng.	DATE 9/6/89
I hereby certify that the	information aboys is true and complete to the best of my	knowledge and belief.	

DISTRICT I SUPERVISOR

SEP 1 1 1989

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: