

|                        |  |  |
|------------------------|--|--|
| NO. OF COPIES RECEIVED |  |  |
| DISTRIBUTION           |  |  |
| SANCTA FE              |  |  |
| FILE                   |  |  |
| U.S.G.S.               |  |  |
| LAND OFFICE            |  |  |
| OPERATOR               |  |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR APPLICATIONS TO OBTAIN OR TO REOPEN OR REEVALUATE A DIFFERENT RESERVOIR. SEE APPLICATION FOR PERMIT - 11-1001-1-1001 FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator  
**TEXACO Inc.**

3. Address of Operator  
**P. O. Box 728 - Hobbs, New Mexico 88240**

4. Location of Well  
UNIT LETTER **B** **1980** FEET FROM THE **East** LINE AND **660** FEET FROM  
THE **North** LINE, SECTION **16** TOWNSHIP **23-S** RANGE **37-E** NMPM.

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
**B-158**

7. Unit Agreement Name  
**-**

8. Farm or Lease Name **NCT-8**  
**New Mexico 'BZ' St.**

9. Well No.  
**6**

10. Field and Pool, or Valued  
**Langlie Mattix Seven Rivers Queen**

12. County  
**Lea**

15. Elevation (Show whether DF, RT, GR, etc.)  
**3319' (DF)**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO:                                                     | SUBSEQUENT REPORT OF:                                |
|-----------------------------------------------------------------------------|------------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/>                              | REMEDIAL WORK <input type="checkbox"/>               |
| TEMPORARILY ABANDON <input type="checkbox"/>                                | COMMENCE DRILLING OPS. <input type="checkbox"/>      |
| PULL OR ALTER CASING <input type="checkbox"/>                               | CASING TEST AND CEMENT JOBS <input type="checkbox"/> |
| OTHER <input checked="" type="checkbox"/> <b>Convert to Water Injection</b> | OTHER <input type="checkbox"/>                       |
| PLUG AND ABANDON <input type="checkbox"/>                                   | ALTERING CASING <input type="checkbox"/>             |
| CHANGE PLANS <input type="checkbox"/>                                       | PLUG AND ABANDONMENT <input type="checkbox"/>        |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Install BOP. Pull production equipment.
2. Clean out to TD (3660').
3. Perforate 4-1/2" OD csg w/2 JSPF from 3482-3484' & 3515-3517'.
4. Set pkr. @ 3450'. Acidize perforations 3482-3608' w/1500 gals. regular mud acid in 3 equal stages w/250# Rock Salt between stages.
5. Run 2-3/8" OD tubing (internally plastic coated) w/packer & set @ 3400'.
6. Load casing annulus w/inhibited water.
7. Test and place well on injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE Asst. District Supt. DATE 11-29-76

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: