COPY TO U. C. C. Form 9-331 (May 1963) TED STATES Form approved. Budget Bureau No. 42-R1424. SUBMIT IN TRE ^ATE\* DEPARTML OF THE INTERIOR (Other instruction verse side) 5. LEASE DESIGNATION AND SERIAL NO. **GEOLOGICAL SURVEY** LC 054453 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS o mett i n esu ikutte ikutte (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME WELL P & A \. | 8 8 6 | 8 8 7 GAS WELL OTHER ي ≾ ي 2. NAME OF OPERATOR 8. FARM OR LEASE NAME James H. Duthie WN Atlantic Richfield Company Bat. 3. ADDRESS OF OPERATOR 9. WELL NO. 2 2 3 P. O. Box 1978, Roswell, New Mexico, 88201 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface 10. FIELD AND POOL, OR WILDCAT Langlie Mattix-Queen SEC., T., R., M., OR BLK. AND SURVEY OR AREA 660' FNL & 660' FEL (Unit Letter A) 2 19 10 Sec. 19,2T23S, R37E 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 12. COUNTY OR PARISH 13. STATE 6.2 E 3327' DF Lea 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: €3 % 5° mai TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON\* X SHOOTING OR ACIDIZING ABANDONMENT\* REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent. proposed work. If nent to this work.) \* i (ogi This well has been plugged & abandoned in the following manner: Set CIBP @ 3385', capped w/6 sx cement. Unable to pull any 5½" Set 35 sk cement plug from 934' to 1234' Erected dry 5½" casing hole marker w/10 sx cement in top of well. na pej romor romor romor romor casing remain intact. Well P & A 7/7/71. Your office will be notified when location is ready for

18. I hereby certify that the foregoing is true and correct SIGNED

TITLE Dist. Drlg. Supervisor

DATE

न हुई इ

anion T bas

1 010 6 38.0 87.0 87.0

a Isto State State incal,

abanded

٠.

3

៊ី

93673

3

nethori

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

15 B 85 9

JUL 1

\*See Instructions on Reverse Side