

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

0+2 — P.O. BOX 1980
HOBBS, N.M. 88240 (LEA COUNTY)

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDARY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR OPERATIONS TO BE PERFORMED ON DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL C-102 FOR SUCH OPERATIONS.)		5a. Indicate Type of Lease State ☐ Fee ☒ 5. State Oil & Gas Lease No.
1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>Plugged & abandoned well</u> 2. Name of Operator <u>Getty Oil Company</u> 3. Address of Operator <u>P. O. Box 730, Hobbs, New Mexico 88240</u> 4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660'</u> FEET FROM THE <u>West</u> LINE, SECTION <u>20</u> TOWNSHIP <u>23S</u> RANGE <u>37E</u> NMPM.	7. Unit Agreement Name 8. Farm or Lease Name <u>Steeler</u> 9. Well No. <u>12</u> 10. Field and Pool, or Wildcat	
15. Elevation (Show whether DF, RT, CR, etc.)		12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	1-R.J. STARRAK-TULSA	☐ ☐ ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	1-A.B. CARY-MIDLAND	
PULL OR ALTER CASING ☐		1-E. Buttross, ENGINEER	
		1-H.C. Little, FOREMAN - MLMU	
OTHER <u>Reenter and replug</u> ☒		1-FILE	

0- _____, WIO's -LIST ATTACHED

1-BH, FIELD CLERK

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

According to the NMOCC Order No. 460 for the expansion of our Myers Langlie Mattix Unit, this well must be properly plugged before water can be injected within a 1/2 mile radius. We plan to reenter and replug the well using the following procedure.

1. Rig up pulling unit and install BOP.
2. Drill out cement plugs surface-300', at 1200', and at 2600'.
3. Go to 3515' and displace hole with 10# mud.
4. Spot 40 sxs. cement plug 3315-3515' over 7" casing shoe at 3465'.
5. Spot 40 sxs. cement plug 2449-2549' over 7" casing cutoff at 2499'.
6. Spot 100 sxs. cement plug 1200-1300' over top of salt.
7. Spot 40 sxs. cement plug 644-744' over 9 5/8 casing shoe at 694'.
8. Spot 20 sxs. cement plug surface-50'.
9. Install marker.

THE COMMISSION MUST BE NOTIFIED
24 HOURS PRIOR TO COMMENCING WORK

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: Dan H. Parker TITLE: Area Superintendent DATE: 8-17-78

APPROVED BY: AUG 21 1978 TITLE: Jerry Seaton DATE: _____

CONDITIONS OF APPROVAL, IF ANY: Dist 1. Sup.