

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBBS OFFICE O.C.C.
NEW MEXICO OIL CONSERVATION COMMISSION

APR 4 8 04 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Saltmount
9. Well No. 1
10. Field and Pool, or Wildcat Teague McKee
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Gulf Oil Corporation 3. Address of Operator P. O. Box 980, Kermit, Texas 4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>21</u> TOWNSHIP <u>23 S</u> RANGE <u>37 E</u> N.M.P.M.	15. Elevation (Show whether DF, RT, GR, etc.) 3303' GR
---	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up casing pullers, pulled 75,000#, unable to unseat Sweet packer @ 9155', shot off tubing @ 9100'. Placed 40 sacks cement 9100-8875'. Displaced hole with mud, recovered estimated 80 barrels oil. Pulled tubing. Shot 7" casing @ 3742', pulled 87 jts. Spotted 50 sacks cement 3767-3632'. Shot 9-5/8" casing @ 1100', could not pull, tried 3 additional shots coming up hole. Finally shot off @ 300' and pulled 10 jts. Spotted 25 sacks cement 2922-2887'; mud to 336'; 50 sacks cement to 266'; mud to 50' and cement to surface. Leaving 311' of 13-3/8", 2602' of 9-5/8" and 5858' of 7" casing in hole. Set well marker.

Location is cleaned up and ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. W. Whitaker TITLE Area Engineer DATE April 1, 1966

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: