NOLTUE			Form C-103	
331708				
			Supersedes	Old
	NEW MEXICO OIL CON	SERVATION COMMISSION	C-102 and	
1 1			Effective 1	-1 - 65
			5a. Indicate Ty	pe of Lease
)FFICE			State	Fee X
OR		,	5 51515 011 5	
			5. State Oil & C	jas Lease No.
w	program and the second	The state of the s		
SUNDR	Y NOTICES AND REPORTS OF	JWELLS	1111111	THITTE
USE "APPLICATE	Y NOTICES AND REPORTS OF POSALS TO DRILL OR TO DESPEN OR PLUG ON FOR PERMIT -" (FORM C-101) FOR SL	BACK TO A DIFFERENT RESERVOIR.		
	The state of the s	CH PROPUSALS.)	11111111	777/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1
GAS WELL			7. Unit Agreem	ent Name
an. of Operator	OTHER-		1	
and St Operator		and the same of th	8. Farm or Leas	se Name
Millard Deck				1
i. ress of Operator		the second secon	May /	<u>t</u>
			9. Well No.	
P. O. Box 1047, Funice,	N.M. 88231		A 1.7	i
4. Location of Well		ph. In 1999, 1999, where the register a highest phase annual programming the state of the state	10. Field and P	and an Maria
	_		10. Tield and P	ool, or wildcat
UNIT LETTER 198	60 FEET FROM THE East	LINE AND 1980 FEET FE	Langli	le Mattix
			MITTER	
THENorth LINE. SECTION	21 TOWNSHIP 23S	27t		
	TOWNSHIP 238	RANGE J/B NM	PM. ()	
	15. Elevation (Show whether	DE DE OB		77777777
	15. Elevation (show whether	FDF, RT, GR, etc.)	12. County	
<i>711 11 11 11 11 11 11 11 </i>	3318'		Lea	
Check A				_777777777777
NOTICE OF THE	ppropriate Box To Indicate N	vature of Notice, Report or (Other Data	
NOTICE OF IN	TENTION TO:	SUBSEQUE	NT REPORT OF	•
				•
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEUIAL WORK		
TEMPORARILY ABANDON X	The Market of	REMEDIAL WORK	ALTE	RING CASING
<u> </u>		COMMENCE DRILLING OPNS.	PLUG	AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB		
		CT:FR		
OTHER	The state of the	CT :ER		
	rations (Clearly state all pertinent dete			
7. Describe Proposed or Completed Ope wark) SEE RULE 1103. 1. Close valve. 2. Poseible work over				