

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Corp.  
P.O. Box 1980  
Hobbs, NM 88241

Division

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

Lease Designation and Serial No.

NMLC - 030187

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

C. E. Lamunyon #7

9. API Well No.

30-025-10828

10. Field and Pool, or Exploratory Area

TEAGUE SIMPSON

11. County or Parish, State

LEA COUNTY, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of well

☒ Oil ☐ Gas ☐ Other

2. Name of Operator

ARCH PETROLEUM, INC.

3. Address and Telephone No.

10 Desta Dr. Suite 420E, Midland, TX 79705 (915) 685-1961

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit M, 660' FSL, 660' FWL, Sec. 22, T23S, R37E

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

12 TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Required Pressure Test

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimate date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU PU. NDWH NU BOP. DMP 8 SX CMT ON CIBP @ 5345'. SET CIBP @ 6700' CAPPED W/ 35' CMT. DETERMINED FREE PT IN 7" CSG @ 4925'. ND BOP. SHOOT OFF CSG @ 4925'. NU BOP. SET CMT STUB PLUG @ 4925'-50 IN & 50 OUT. SET CMT SHOE PLUG @ 2900'-50 IN & 50 OUT. SET 25 SX CMT PLUG @ 2450, & 1400'. DETERMINED FREE PT IN 9 5/8" CSG @ 880'. ND BOP. SHOOT OFF CSG @ 880'. SET CMT STUB PLUG @ 880'-50 IN & 50 OUT. SET 25 SX CMT PLUG @ 350'. SET 10 SX CMT PLUG @ SURFACE (DISPLACED BETWEEN PLUGS W/ 10# BRINE/ 25# GEL PER BBL). ND BOP & RD PU.

SEE ATTACHED FOR  
CONDITIONS OF APPROVAL

RECEIVED  
1997 JUL -9 A 9:41  
BUREAU OF LAND MGMT.  
ROSWELL OFFICE

14. I hereby certify that the foregoing is true and correct

Signed

Title

AGENT

Date

7/7/97

(This space for Federal or State office use)

(ORIG. SGD.) ALEXIS C. SWOBODA

PETROLEUM ENGINEER

Approved by

Date JUL 10 1997

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instructions on Reverse Side