Use "APPLICATION FOR PERMIT-" for such proposals N/A SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement Designation 1. Type of well N/A X_Oil Gas Other 8. Well Name and No. 2. Name of Operator LA MUNYON FED. #2 CHEVRON U.S.A. INC. 9. API Well No. 3. Address and Telephone No. 915-687-7436 30-025-10838		IENT OF	STATES THE INTERIOR MANAGEMENT		Budget Bure Expires: N	APPROVED au No. 1004-0135 larch 31, 1993	
SUBMIT IN TRIPLICATE 7. If Unit or CA. Agreement Designation 1. Type of World Gas Other 2. Name of Operator 0. Well Name and No. 2. Name of Operator E. API Well Name and No. 2. Name of Operator B. API Well Name and No. 2. Name of Operator B. API Well Name and No. 3. Oddress and Theoremone No. 915-687-7436 1. Operation of Well Proceedings Sec. Tr. R. M. or Survey Description Sec. 22, 7235, R37E 3. Operation of Well Proceedings Sec. Tr. R. M. or Survey Description Sec. 22, 7235, R37E 3. Operation of Well Proceedings Sec. Tr. R. M. or Survey Description Sec. 22, 7235, R37E 3. Operation of Well Proceedings Sec. Tr. R. Operator Area LANGLIE MATTIX Sec. 22, 7235, R37E Sale Sec. Tr. R. State 3. Operation of Well Proceedings Sec. Tr. R. Operator Area LANGLIE MATTIX Sec. 22, 7235, R37E Sale Sec. Tr. R. State Langlie Mattix Sec. 22, 7235, R37E Sale Sec. Tr. R. State Langlie Mattix Sec. 22, 7235, R37E Sale Sec. Tr. R. Operator Area Langlie Mattix Sec. 21, 724, 725, 725 Sale Sec. 70 Conter of Profile Sec. 70 Sec. 21, 725, 725 Sale Sec. 71, 725 Conter of Profile Sec. 70 <td>SUNDRY NOTICES AI</td> <td>ND REPOI</td> <td>RTS ON WELLS</td> <td></td> <td>-</td> <td></td>	SUNDRY NOTICES AI	ND REPOI	RTS ON WELLS		-		
SUBMIT IN TRIPLICATE 1. Type of wolf 0 as	Do not use this form for proposals to drill or deepen or reentry to a different rese				6. If Indian, Allot	tee or Tribe Name	
	Use "APPLICATION	FOR PER	MIT-" for such pr	oposals	N/A		
Image: a construction 8. Well Reme and No. 2. Home and Operator CHEVRON U.S.A. INC. 3. Address and Operator 9. API Well No. 3. Address and Telephone No. 915-687-7436 P.O. BOX 1150 MIDLAND, TEXAS 79702 ATTN: NITA RICE 10. Field and Pool, or Exploratory Area 4. Location of Wirdordag. Sec. 12, R. M. or Survey Description) LANGLE MANTIX SEC. 22, T23S, R37E 11. Country or Parish. State 330' FNL & 990 FVU LLA COUNTY, NEW MEXICO UNIT D CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 13 TYPE OF SUBMISSION TYPE OF ACTION Wire State Change of Plans Becompletion Propaging Back Noncirce of Intern Subsequent Report Change of Plans New Construction Subsequent Report Casing Repair Ware Shurd 13. Data a Proposed or Completed Distate Order State and particle Market and and and the indicate one wire complete on wire complete one wir						Agreement Designation	
						d No.	
CITECTURE INTO THE POOL OF EXPLORED TO THE POOL OF EX	2. Name of Operator				LA MUNYON	I FED. #2	
P.O. BOX 1150 MIDLAND, TEXAS 79702 ATTN: NITA RICE 10. Feld and Pool, or Exploratory Area 4. Location of Well (Footage, Sec. T, R, M, or Survey Description) LANGLIE MATTIX SEC. 22, T23S, R37E LANGLIE MATTIX 330° FNL & 990 FWL LI Country or Parks, State UNIT D CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Bodie of Intent Abandomment Check Appropriate Boxics) Date of Intent Worke of Intent Abandomment Report Casing Repair Date of Ornotice Fractuling Casing Repair Casing Repair Device Arosenese of Constructs Clearly task at a diment latest, and grup partners date, including etwarts at all material and provided one of the second of the s	CHEVRON U.S.A. INC.				9. API Well No.		
4. Location of Well if Gottage, Sec. T., R., M., or Survey Description) LANGLIE MATTIX SEC. 22, 7233, R37E 11. County or Parets, State 330' FNL & 990 FWL LANGLIE MATTIX UNIT D CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Image: State	3. Address and Telephone No.		915-687-7436		30-025-1	0838	
	P.O. BOX 1150 MIDLAND, TEXAS 79702	ATTN: NI	TA RICE		10. Field and Poo	bi, or Exploratory Area	
330' FNL & 990 FWL UNIT D LEA COUNTY, NEW MEXICO CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF SUBMISSION OF ACTION Other Colspan="2">Change of Plans Notice of Intent Abandonment Notice Other Other Other Other Notice of Intent Other Other Notice Plans Other Notice of Intent Other Notice of Intent Other Notice of Intent Other Notice of Intent Other Other Notice of Intent A Dispose Water Other Other Other Other <td col<="" td=""><td>4. Location of Well (Footage, Sec., T., R., M., or Survey Des</td><td>cription)</td><td></td><td></td><td>LANGLIE</td><td>ΜΑΤΤΙΧ</td></td>	<td>4. Location of Well (Footage, Sec., T., R., M., or Survey Des</td> <td>cription)</td> <td></td> <td></td> <td>LANGLIE</td> <td>ΜΑΤΤΙΧ</td>	4. Location of Well (Footage, Sec., T., R., M., or Survey Des	cription)			LANGLIE	ΜΑΤΤΙΧ
UNIT D CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF ACTION Abandonment Abandonment Abandonment Abandonment Abandonment Notice Final Abandonment Notice Tinal Abandonment Notice Attemp Casing Attemp Cas	SEC. 22, T23S, R37E				11. County or Pa	rish, State	
CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12 TYPE OF SUBMISSION 12 TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Advance of Plans Recompletion The Abandonment Plugging Back Optimize of Notice of Intent Optimize of Conversion to Injection The Abandonment Plug ing Back Optimize of Conversion to Injection Optin (Sign Officolspan") FROM 3520'. 20.92	330' FNL & 990 FWL				LEA COU	NTY, NEW MEXICO	
12 TYPE OF SUBMISSION TYPE OF ACTION Image: Subsequent Report Image: Adaption ment image: Additimage: Adaptimage: Addition ment image: Addited image: A							
Notice of Intent Notice of Intent Abandonment Casing Repair New Construction Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Antering Casing Conversion to Injection Title Conversion to Injection Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Antering Casing Conversion to Injection Notice of Completed Operations (Clearly state all performer details, and give performer dates, including estimate date of stating way proposed work. If well a directionally drilled.	CHECK APPROPRIATE	BOX(S) T				RT, OR OTHER DATA	
Bubsequent Report Subsequent Report Subsequent Report Final Abandonment Notice Bina Abandonment Noting Nationa Abandonmen	TYPE OF SUBMISSION		TYPE C	OF ACTION			
Yes Subsequent Report Plugging Back Non-Routine Fracturing Principal Abandonment Notice Page 201 Conversion to Injection Casing Repair Page 201 Conversion to Injection Title Page 201 Page 201 Page 201 Page 201 Page 201 Page 201 Page 201 The AND TAG CIEP AT 3520°. DISP HOLE W/10# MUD. PRESSURE TEST TO 300 PSI, OK. Sport 30 SX PLUG (370') FROM 3520-3250. SPOT 60 SX CL-C PLUG FROM 2890-2310° (580'). PERF 4 HOLES @ 1255', SET CICR 1000', SQZ 105 SX CMT BELOW W/300 PSI, STING OUT, DUMP 35' CMT ON TOP. PERF 4 HOLES @ 376, SQZ 70 SX CMT BELOW & DISP CMT TO 200'. SPOT 15 SX CMT F/96' TO SURF. POH, ND BOP, FILL HOLE W/CMT. BLM REP STEVE CAFFIE ON LOCATION DURING P&A OPERATIONS. CUT OFF WELLHEAD & INSTALL P&A MARKER. CHANGE WELL STATUS TO P & A. Approximation for adverted bards at the second bards as the defeed of starting any proposed wate and the second bards as the defeed of start and and prove the placed. 11. Interdev centre total and measured and the second bards as the defeed of start and prove the placed. Date 10/14/92 The TECHNICAL ASSISTANT Date 10/14/92 Date 10/14/92	Notice of Intent		Abandonment		Change of F	Plans	
Casing Repair Conversion to Injection Conversion Conversion to Injection Conversion Conversion to Injection Conversion Conver			Recompletion		New Constr	uction	
Altering Casing Ander P & A Dispose Water More P & A Dispose Water More means of moment and measured and true vertical depths for all markers and zones performent dates, including estimate date of starting any proposed work. If well is directionally diffed. WORK DONE 9-22-92 THRU 9-23-92 TH AND TAG CIBP AT 3520'. DISP HOLE W/10# MUD. PRESSURE TEST TO 300 PSI, OK. SPOT 30 SX PLUG (370') FROM 3520-3250. SPOT 60 SX CL-C PLUG FROM 2890-2310' (580'). PERF 4 HOLES @ 1255', SET CICR 1000', SOZ 105 SX CMT BELOW W/300 PSI, STING OUT, DUMP 35' CMT ON TOP. PERF 4 HOLES @ 376, SOZ 70 SX CMT BELOW & DISP CMT TO 200'. SPOT 15 SX CMT F/96' TO SURF. POH, ND BOP, FILL HOLE W/CMT. BLM REP STEVE CAFFIE ON LOCATION DURING P&A OPERATIONS. CUT OFF WELLHEAD & INSTALL P&A MARKER. CHANGE WELL STATUS TO P & A. The TECHNICAL ASSISTANT Date 10/14/92 This Date 10/14/92 This TECHNICAL ASSISTANT Date 10/14/92 This TECHNICAL ASSISTANT Date 10/14/92 This Date 10/14/92 This TECHNICAL ASSISTANT Date 10/14/92 This Date 10/14/94 Th	Subsequent Report		Plugging Back		Non-Routine	e Fracturing	
			Casing Repair		Water Shut-	Off	
	Final Abandonment Notice		Altering Casing		Conversion	to Injection	
Concernation or Recomparison Report and Log form.] Concernation or Recomparison Report and Log form.] Concernation Report and Log			X Other	P & A	· ·		
give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.1* WORK DONE 9-22-92 THRU 9-23-92 TIH AND TAG CIBP AT 3520'. DISP HOLE W/10# MUD. PRESSURE TEST TO 300 PSI, OK. SPOT 30 SX PLUG (370') FROM 3520-3250. SPOT 60 SX CL-C PLUG FROM 2890-2310' (580'). PERF 4 HOLES @ 1255', SET CICR 1000', SQZ 105 SX CMT BELOW W/300 PSI, STING OUT, DUMP 35' CMT ON TOP. PERF 4 HOLES @ 376, SQZ 70 SX CMT BELOW & DISP CMT TO 200'. SPOT 15 SX CMT F/96' TO SURF. POH, ND BOP, FILL HOLE W/CMT. BLM REP STEVE CAFFIE ON LOCATION DURING P&A OPERATIONS. CUT OFF WELLHEAD & INSTALL P&A MARKER. CHANGE WELL STATUS TO P & A. Approver back and the toppoing is true where Title TeCHNICAL ASSISTANT Date 10/14/92					Completion or Recomple	etion Report and Log form.)	
Signed Muta Kuck Title TECHNICAL ASSISTANT Date 10/14/92 (This space for Federal or State office use) Approved by	TIH AND TAG CIBP AT 3520'. DISF SPOT 30 SX PLUG (370') FROM 35 2890-2310' (580'). PERF 4 HOLES W/300 PSI, STING OUT, DUMP 35' CMT BELOW & DISP CMT TO 200'. W/CMT. BLM REP STEVE CAFFIE C CUT OFF WELLHEAD & INSTALL P&	P HOLE W 20-3250. @ 1255' CMT ON SPOT 15 DN LOCAT	SPOT 60 SX CL-(, SET CICR 1000' TOP. PERF 4 HO SX CMT F/96' T TON DURING P&A	C PLUG FI , SQZ 105 LES @ 370 O SURF. P O OPERATI	ROM SX CMT BE 5, SQZ 70 S OH, ND BOP ONS.	LOW X 2, FILL HOLE Class word Laray Calancia undik	
Approved by							
Approved by Conditions of approval, if any:	VIII. KIAA	Title	TECHNICAL AS	SISTANT	Date	10/14/92	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fictitious or fraudulent statements	Signed Alta Rice	Title	TECHNICAL AS	SISTANT		1	
	Signed Mathematical State (This space for Federal or State office use) Approved by		TECHNICAL AS	SISTANT			
or representations as to any matter within its jurisdiction.	Signed Mathematical State (This space for Federal or State office use) Approved by		TECHNICAL AS	SISTANT		1	
	Signed <u>Muta</u> <u>Kuse</u> (This space for Federal or State office use) Approved by Conditions of approval, if any:	Title			Date(_((29/92	

1 310

S