

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

LC-032545-451, 5/12/77

DURAND NOBLES AND REPORTS ON WELLS

(This form is to be filled out by the well owner or plug back to a different owner. It is not to be filled out by the BLM. INFORMATION FOR PERMITTEE for each production)

Toraco Inc.

U.S. Geological Survey
P.O. Box 10000
Denver, CO 80260

P. O. Box 720, Hobbs, New Mexico 88240

San Jose, California
P.O. Box 10000
Denver, CO 80260

Unit: Totten R, 1980 feet from the south line and
650 feet from the west line

20-4-223-1-220

31-025-10644

3765' DE

20-4-223-1-220

Unit: Totten R, 1980 feet from the south line and
650 feet from the west line

1. Big-up piling unit and install 100'.
2. UH with workstring and circulate 10#/gallon brine.
3. Spot a 75' cement plug on top of 5-1/2" CIBS at 1430'. (Use
Class "H" cement with 2% CACL)

4. Pull up and spot a 100' cement plug from 1125 to 1250'.

5. Pull up and set a 100' cement plug at surface and install
dry hole marker.

Dist. Opr. No.

12-45-55

APPROVED BY

TITLE

2-10-84

*See Instructions on Reverse Side

RECEIVED
FEB 12 1986
C.C.P.
HOBBS OFFICE