

EXICO OIL CONSERVATION COMM. SION

SANTA FE, NEW MEXICO

## **MISCELLANEOUS NOTICES**

APR 1 1 1951

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work in the begin. A copy will be returned to the sender on which will be given the approval, with any additional considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved spice and work should not begin until approval is obtained. See additional instructions in the Fules and regulations of

Indicate nati	ure of not	ce by checking below:		
OTICE OF INTENTION TO TEST CASING SHUT-OFF	7 <sup>11</sup>	NOTICE OF INTENTION CHEMICALLY TRI		
OTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION		
OTICE OF INTENTION TO REPAIR WELL		NOTICE OF INTENTI	ON TO PLUG WELL	
OTICE OF INTENTION TO DEEPEN WELL		=	*****	
	Hobbs	, New Mexico	April 10,	1951
		Place	Date	
nta Fe, New Mexico entlemen:  ollowing is a notice of intention to do certain wo	ork as des	cribed below at the	2	NV SE
Gulf Oil Corporation  Company or Operator	ease		Well Noin	
Company or Operator 27	E	N. M. P. M., Teagus-	-Ellemburger	Fiel
Lea Coun				
	0.00	DOGED DI 111 OF III	ODIZ	
On April 7, 1951, ran 251 joint casing from bottom up, 12 joint	e Rules ints, 97	/63', of 7" OD 8 R. 1. 74 joints 26#, 1	THE COMMISSION  T. R-3 N-80 new S  151 joints 23#, 13	3
FOLLOW INSTRUCTIONS IN THE	e RULES ints, 97 ints 29, ith 49 w to 9776	AND REGULATIONS OF (631, of 7" OD 8 R. 1, 74 joints 26#, 1 leatherford scratch 5. Set and cement	THE COMMISSION  T. R-3 N-80 new S  51 joints 23#, 13  ners and 9 Weather  ced at 9779' with	} r••
On April 7, 1951, ran 251 joi casing from bottom up, 12 jei joints 26# and 1 joint 29# wi ford centralizers from 9097' 1175 sacks of 2 per cent Cel	nts, 97 ints 29/ ith 49 w to 9776 bulk co	AND REGULATIONS OF 7% OD 8 R. 4, 74 joints 26#, 1 jeatherford scratch 5. Set and cement ment. Plug at 974	THE COMMISSION  T. R-3 N-80 new S  51 joints 23#, 13  ners and 9 Weather  ced at 9779' with  18'. Job complete	} r•• •
On April 7, 1951, ran 251 joints 26# and 1 joint 29# wiford centralizers from 9097' 1175 sacks of 2 per cent Gel 5:15 p.m. April 7, 1951.	e RULES  ints, 97  ints 29  ith 49 w  to 9776  bulk co	AND REGULATIONS OF (63', of 7" OD 8 R. (63', of 7" OD 8 R. (63', 74 joints 26#, 1 leatherford scratch (6'). Set and cement ment. Plug at 974 of cement behind	THE COMMISSION  T. R-3 N-80 new S  151 joints 23#, 13  ners and 9 Weather  ted at 9779' with  18'. Job complete  7" casing at 4700	} r•• •
On April 7, 1951, ran 251 joint casing from bottom up, 12 joints 26# and 1 joint 29# wi ford centralizers from 9097' 1175 sacks of 2 per cent Cel 5:15 p.m. April 7, 1951.  Ran temperature survey and for Propose to drill plug and teamperous descriptions.	e RULES  ints, 97  ints 29  ith 49 w  to 9776  bulk co	AND REGULATIONS OF (63', of 7" OD 8 R. (63', of 7" OD 8 R. (63', 74 joints 26#, 1 leatherford scratch (6'). Set and cement ment. Plug at 974 of cement behind	THE COMMISSION  T. R-3 N-80 new S  51 joints 23#, 13  ners and 9 Weather  ed at 9779' with  8'. Job complete  7" casing at 4700  11 9, 1951.	} r•• •
On April 7, 1951, ran 251 joint casing from bottom up, 12 joints 26# and 1 joint 29# wi ford centralizers from 9097' 1175 sacks of 2 per cent Cel 5:15 p.m. April 7, 1951.  Ran temperature survey and for Propose to drill plug and teamperous descriptions.	e RULES  ints, 97  ints 29  ith 49 w  to 9776  bulk co	AND REGULATIONS OF (63', of 7" OD 8 R. (63', of 7" OD 8 R. (63', 74 joints 26#, 1 joints 26#, 26#, 26#, 26#, 26#, 26#, 26#, 26#,	THE COMMISSION  T. R-3 N-80 new S  51 joints 23#, 13  ners and 9 Weather  sed at 9779' with  8'. Job complete  7" casing at 4700  11 9, 1951.	} r•• •
On April 7, 1951, ran 251 joint casing from bottom up, 12 joints 26# and 1 joint 29# wi ford centralizers from 9097' 1175 sacks of 2 per cent Gel 5:15 p.m. April 7, 1951.  Ran temperature survey and for Propose to drill plug and teamperous descriptions.  APR 11 1951	e RULES  ints, 97  ints 29  ith 49 w  to 9776  bulk co	AND REGULATIONS OF  (631, ef 7" OD 8 R.  (4, 74 joints 264, 1  (eatherford scratch  (b). Set and cement  (ment. Plug at 974  (c) of cement behind  (c) of 5:15 p.m. April  (c) Gulf Oil Cerp  (c) By  (c) Area Proposition	THE COMMISSION  T. R-3 N-80 new S  51 joints 23#, 13  ners and 9 Weather  ed at 9779' with  8'. Job complete  7" casing at 4700  11 9, 1951.	3 9
On April 7, 1951, ran 251 joint casing from bottom up, 12 joints 26# and 1 joint 29# wi ford centralizers from 9097' 1175 sacks of 2 per cent Gel 5:15 p.m. April 7, 1951.  Ran temperature survey and for Propose to drill plug and test approved.  APR 11 1951	e RULES  ints, 97  ints 29  ith 49 w  to 9776  bulk co	AND REGULATIONS OF  (631, ef 7" OD 8 R.  (4, 74 joints 264, 1  (eatherford scratch  (b). Set and cement  (ment. Plug at 974  (c) of cement behind  (c) of 5:15 p.m. April  (c) Gulf Oil Cerp  (c) By  (c) Area Proposition	THE COMMISSION  T. R-3 N-80 new 3  51 joints 23#, 13  ners and 9 Weather  sed at 9779' with  18'. Job complete  7" casing at 4700  11 9, 1951.	3 9
On April 7, 1951, ran 251 joint casing from bottom up, 12 joints 26# and 1 joint 29# wi ford centralizers from 9097' 1175 sacks of 2 per cent Gel 5:15 p.m. April 7, 1951.  Ran temperature survey and for Propose to drill plug and teampered April 7 plug and teampered at follows:	e RULES  ints, 97  ints 29  ith 49 w  to 9776  bulk co	Gulf Oil Corposition  Gulf Oil Corposition  Area Proposition  Name  Chas. To	THE COMMISSION  T. R-3 N-80 new 3  51 joints 23#, 13  ners and 9 Weather  sed at 9779' with  18'. Job complete  7" casing at 4700  11 9, 1951.	yell to