NG. OF COPIES RECEIVED			Form C+103
DISTRIBUTION			Supersedes Old
SANTA FE	NEW MEXICO OIL CONS	SERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE			
U.S.G.S.			Sa. Indicate Type of Lease
LAND OFFICE	-		State Fee. 🗙
OPERATOR			5. State Oil & Gas Lease No.
SUND	RY NOTICES AND REPORTS ON	WELLS	
(DC NOT USE THIS FORM FOR P USE **APPLICA	RY NOTICES AND REPORTS ON ROPOSALS TO DRILL OR TO DEEPEN OR PLUG E ATION FOR PERMIT -" (FORM C-101) FOR SUC	BACK TO A DIFFERENT RESERVOIR. TH PROPOSALS.)	
1.			7. Unit Agreement Name
WELL WELL	OTHER-		
luames to per the			8. Farm or Lease Name
Gulf Oil Corporation			E. C. Hill (Tr. A)
3. Address of Operator			9. Well No.
P. O. Box 980, Kermit, Texas			4
4, Location of Well			10. Field and Pool, or Wildcat
UNIT CHIMER N			Teague
THE LINE, SECT	TON 27 TOWNSHIP 23-5	RANGE 37-E NMPM	
			ΔΗΗΗΗΗΗΗΗΗΗΗ
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
	<u>3283</u> GR	•	Lea Allilli
Check	Appropriate Box To Indicate N	ature of Notice, Report or Ot	her Data
			T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
FULL OF ALTER CAEING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
	[]	OTHER	
O7HE¥			
T. Completed Completed C	Operations (Clearly state all pertinent dete	ails, and give pertinent dates, including	estimated date of starting any proposed

11. Security Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well was originally completed 2-1-53 in the Teague Ellenburger pay with a plug back depth of 9743'. In 7-6-57 the well was plugged back to the Teague McKee pay by squeezing Ellenburger perforation with 78 sacks of cement. Max. pressure 4000#. Top of plug 9490'. The Teague McKee was uneconomical to produce and was temporarily abandoned 3-24-59.

It is proposed to spot 25 sacks cement @ 9100' (Top of McKee Pay); mud to 5200'; cut  $5\frac{1}{2}$ " casing at approximately 5200' and pull; cement plug 25 sacks at 5200'; mud to 4918'; cement plug 25 sacks at 4918' (Top of Glorieta Pay 4918'); mud to 3920', cement plug 25 sacks at 3920' (Top of Judkins at 3920'); mud to 3365'; cement plug 25 sacks at 3365' (Top of Penrose at 3365'); mud to 2899'; cement plug 25 sacks at 2899' (shoe of 8-5/8" casing); mud to 50'; cement plug 50' to surface; leaving 4542' of  $5\frac{1}{2}$ " casing; 2899' of 8-5/8" casing and 320' of 13-3/8" casing in the hole. Set marker and abandon well leaving location clean.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNED A. T. Swannall	TITLE Area Production Manager	DATE June 8, 1965			
APPROVED BY	TITLE	DATE			

CONDITIONS OF APPROVAL, IF ANY: