Form 9-331 (May 1963)	UNILED STATES	SUBMIT IN TRIPLICATE*	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.			
	DEPARTMENT OF THE INTERIC	OR verse side)				
<u> </u>	GEOLOGICAL SURVEY	LC-030187				
	SUNDRY NOTICES AND REPORTS O se this form for proposals to drill or to deepen or plug ba Use "APPLICATION FOR PERMIT-" for such pro	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
	NELL X OTHER	7. UNIT AGREEMENT NAME				
2. NAME OF OPERA	ATOR	8. FARM OR LEASE NAME				
Gulf Oi	l Corporation	C. E. LaMunyon				
3. ADDRESS OF OP	ERATOR	9. WELL NO.				
P. O. B	ox 670, Hobbs, NM 88240	6				
4. LOCATION OF W See also space	ELL (Report location clearly and in accordance with any S 17 below.)	tate requirements.*	10. FIELD AND POOL, OR WILDCAT			
At surface			North Teague Devonian			
			11. SEC., T., R., M., OB BLK. AND SUBVEY OR ABEA			
766' FN	L & 554' FEL, Section 28, T-23-S, 1					
		Sec 28, T-23-S, R-37-E				
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH 13. STATE			
	3282' GL		Lea NM			
16.	Check Appropriate Box To Indicate Na	iture of Notice, Report, or O	ther Data			
	NOTICE OF INTENTION TO:	SUBSEQU	JENT REPORT OF:			
TEST WATER S	SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL			
FRACTURE TRE	AT MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING			
SHOOT OR ACH	DIZE ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*			
REPAIR WELL	CHANGE PLANS	(Other) Abandon Teag				
(Other)	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)					
17. DESCRIBE PROPO proposed wo nent to this y	NED OR COMPLETED OPERATIONS (Clearly state all pertinent rk. If well is directionally drilled, give subsurface locatio work.)*	details, and give pertinent dates, ns and measured and true vertical	including estimated date of starting any depths for all markers and zones perti-			
	* zone and recomplete in the North					
		onian.				

8-22-77 Pulled Producing equipemnt. Set cement retainer at 8850' and capped with 3 sacks, 35' cement. Abandoning Teague Simpson perfs 9340-9510'. Tested casing and plug with 500# - 0K. Perforated 5" and 7" casing with 2-1/2" JHPF at 7364-69' and perforated 5 1/2" and 7" casing with 1-1/2" JHPF at 7382-87'. Acidized new perfs with 6,000 gallons 15% NEA acid, average treating pressure 2300#. ISIP 1200#, after 5 min 1050#, 15 min 450#. Flushed with 39 bbls 8.6# Brine water. Swabbed and tested. No commerical production. Squeezed perfs 7364-69' and 7382-87' with 150 sacks Class C cement and 100 sacks Class C with 5# sand, 3# salt per sack. Perforated 5" and 7" casing with 2-1/2" JHPF at 7336-42'. Acidized perfs 7336-42' with 4,000 gallons Mod 202 acid, average treating pressure 4775#, average rate 5.3 BPM, flushed with 28 bbls water and overflush with 35 bbls. ISIP 2400#, 15 min 1900#. Swabbed and tested. Frac perfs 7336-42' with 25,000 gallons gelled water containing 3/4# to 1 1/2# 20-40 SPC. Swabbed and cleaned up. Ran 2 3/8" tubing set at 7302' with packer at 7302'. Swabbed 14 bbls load water and swabbed dry. Complete 10-23-77.

Recomplete in North Teague Devonian unsuccessful. Closed in pending well study.

18. I hereby certify that the foregoing is true and correct SIGNED . R. Sulles A.	TITLE Area	Engineer	OB RECORDOARE	10-25-77
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY : *Se	TITLE	U. S. GEOL Reverse Side	G 1977 OGICAL SURVER NEW MEXICO	