

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

0+2 — P.O. BOX 1980
HOBBS, N.M. 88240 (LEA COUNTY)

5a. Indicate Type of Lease	State ☐	Fee ☒
5. State Oil & Gas Lease No.		

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR RE-PLUG A WELL IN A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.		
1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER- <u>Plugged & abandoned well</u>	7. Unit Agreement Name	
2. Name of Operator <u>Getty Oil Company</u>	8. Form of Lease Name <u>Cowden</u>	
3. Address of Operator <u>P. O. Box 730, Hobbs, New Mexico 88240</u>	9. Well No. <u>2</u>	
4. Location of Well UNIT LETTER <u>0</u> <u>1780</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM <u>South</u> THE LINE, SECTION <u>30</u> TOWNSHIP <u>23S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat	
11. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER <u>Reenter and replug</u> ☒	PLUG AND ABANDON ☐ CHANGE PLANS ☐	1-R.J. STARRAK-TULSA 1-A.B. CARY-MIDLAND 1-E. Buttross, ENGINEER 1-H.C. Little, FOREMAN - MLMU 1-FILE 0- _____, WIO's -LIST ATTACHED 1-BH, FIELD CLERK

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

According to the NMOC Order No. 460 for the expansion of our Myers Langlie Mattix Unit, this well must be properly plugged before water can be injected within a 1/2 mile radius. We plan to reenter and replug the well using the following procedure:

1. Rig up pulling unit and install BOP.
2. Drill out cement plug 1175-1200'.
3. Go to 5 1/2" casing cutoff at 3000'.
4. Displace hole with 10# mud.
5. Spot 30 sxs. cement plug 2950-3050' over 5 1/2" casing cutoff at 3000'.
6. Spot 30 sxs. cement plug 1166-1266' over 8 5/8" casing shoe at 1216'.
7. Spot 20 sxs. cement plug surface-50'.
8. Set marker.

THE COMMISSION MUST BE NOTIFIED
24 HOURS PRIOR TO COMMENCING WORK

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Nat'l. Comm.</u>	TITLE <u>Area Superintendent</u>	DATE <u>8-17-78</u>
APPROVED BY <u>Jerry Sexton</u>	TITLE _____	DATE <u>AUG 21 1978</u>
CONDITIONS OF APPROVAL, IF <u>Dist. L. Supv.</u>		