Submit 3 Copies To Appropriate District Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 South First, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505	State of Energy, Minerals OIL CONSERV 2040 Sc Santa Fe	and Nat VATION bouth Pac	ural Resources N DIVISION sheco	5. Indicate Type STATE	- 10932		
SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR. USE "APPLICATI PROPOSALS.) 1. Type of Well: Oil Well Gas Well	7. Lease Name or Unit AgreementName: MYERS LANGLIE MATTIX UNIT						
2. Name of Operator OXY USA W	8. Well No.	53					
OXY USA WTP Limited Partnership 192463 3. Address of Operator				9. Pool name or			
P.O. BOX 50250 MIDLAND, TX 79710-0250				LANGLIE MATTIX 7RVR-QN-GB			
Unit Letter <u>C</u> : <u>660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>33</u> Township <u>235</u> Range <u>37E</u> NMPM County LEA 10. Elevation (Show whether DR, RKB, RT, GR, etc.)							
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
	NTION TO:	iicate Na		SEQUENT RE		s 🗆	
TEMPORARILY ABANDON	IANGE PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND		
	JLTIPLE DMPLETION		CASING TEST ANI CEMENT JOB		ABANDONMENT	Ø	
OTHER:			OTHER:				
12 Describe and 1 1							

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See other Side

Ż

y with rul

I hereby certify that the information above is true and comp	plete to the best of my knowledge and belief	· · ·
SIGNATURE	TITLE REGULATORY ANALYST	DATE ZIMIO
Type or print name DAVID STEWART		Telephone No.915-685-5717
(This space for State use) APPPROVED BY		
Conditions of approval of any:	TITLE Flor Rep	DATE <u>4-24-01</u>
GWW		

MLMU # 53

12/7/2000

MIPU NDWH NU BOP. TIH w/csg scraper and 106 jts tbg to 3349. POOH SION

12/8/2000

TIH w/CIBP and 106 jts set at 3333. Fill and circ well w/brine and test csg. Csg Leaked. POOH. TIH w/pkr and find holes at 954 to 984. POOH. TIH open ended w/106 jts and cmt from 3333 to 2800 w/56 sks cmt followed by 16.2 bbls of displacement. POOH to 2800 mix and pump 25 sks salt gel. POOH. SION

12/11/2000

Perf at 1350. WOC. Cmt w/30 sks of cmt and 9.9 bbls displacement. SION

12/12/2000

TIH and TOC 1246. POOH. TIH w/pkr and 23 jts. Inj rate 300# @ 2 bpm. Cmt w/ 250 sks cmt. While circ to surf ran out of cmt before surf. Disp w/7 bbls POOH SION.

12/13/2000

TIH and TOC 830 w/26 jts. POOH Perf at 315. TIH w/ cmt ret and 6 jts tbg and set 197. Cmt with 105 sks under ret and circ to surf. POO Ret and mix pump 20 sks cmt to fill inside csg. POOH. Fill csg w/cmt. NDBOP RDPU Clean and Clear Locatoin. Well Plugged. Est \$19,500

Newled Stewart