

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPI
(Other instructions
verse side)FE*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

10 064118

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

E. C. Hill "B" Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Teague Ellenburger

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec 34, T-23-S, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Carter Foundation Production Company

3. ADDRESS OF OPERATOR

P. O. Box 900, Kermit, Texas 79745

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)At surface 1,831 feet from North Line and 660 feet from East Line,
of Section 34, T-23-S, R-37-E, Lea County, New Mexico.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3,271 DF, 3,258 OR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Work started 1-6-75. Set AZ drill Bridge Plug at 9,200'.

Displaced fluid in hole with mud, put 25 sack cement plug on bridge plug.

Put 25 sack cement plug 7,107 to 7,000'.

Cut 7" casing at 3,333 and pulled. Ran 250 sack cement plug at 3,417, cement went
down to 4,872. Cemented with 250 sacks cement, found top of cement at 3,572'. Cemented
with 250 sacks cement, top of plug at 2,577'. Cemented with 250 sacks cement, top of
cement at 2,400'.

Cut and pulled 386' of 9-5/8" casing, put 70 sack cement plug from 403' back to 300'.

Put marker at top of well with 10 sack cement plug. Work complete 1-22-1975.

Will notify when clean up is made.

18. I hereby certify that the foregoing is true and correct

SIGNED

E. C. Hill

TITLE

Production Superintendent

DATE

2-24-1975

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE

MAY 18 1977

BERNARD MOROZ

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

4. If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State Federal office for specific instructions.

17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1972-21/207 REGION NO. 8

RECEIVED

MAY 24 1977

U.S. DEPARTMENT OF COMMERCE
BUREAU OF OCEANOGRAPHY