

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPI
(Other instructions
verse side)

CE*
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Las Cruces 06/116

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

UNITED STATES GEOLOGICAL SURVEY

3. ADDRESS OF OPERATOR

Box 900, Arenal, Texas 79745

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

**1981 feet from North line and 810 feet from East line
of Sec. 34, T-23-N, R-37-E, Las Cruces, New Mexico**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3275 RKB 3261 GR

7. UNIT AGREEMENT NAME

Teague Library

8. FARM OR LEASE NAME

Sec. 34, T-23-N, R-37-E

9. WELL NO.

12

10. FIELD AND POOL, OR WILDA

Las Cruces

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 34, T-23-N, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

**On May 16, 1974, pulled tubing and cemented with 35 sacks cement from 7100 to 7225.
Then Gamma Ray - Neutron survey from 5000' to 5700'. Set 22 drill mast iron bridge
plug at 5850' and put 2 sacks cement on top of plug. Perforated with two 1/2" holes
at 5290, 5300, 5325, 5375, 5380, 5542, 5552, 5570, 5580, 5587, 5592, 5615, 5619,
5650, 5660, 5665, 5675, 5690, 5703, 5720, 5733, 5745, 5762, and 5782. Acidized
well with 5000 gallons 15% acid, ran tubing and tested well. Pulled tubing and
fraced well with 54,000 gallons gelled water and 67,500 20/40 sand. Ran tubing
and snabbed well. Work complete 5-22-74.**

**Having trouble keeping well flowing for 24 hours for test. Form 9-330 will
follow as soon as well test is completed.**

ILLEGIBLE

18. I hereby certify that the foregoing is true and correct

SIGNED

E. L. Smith

TITLE

Production Superintendent

DATE

6-7-1974

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

JUN 10 1974

**U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO**

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant contents, sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; point, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-665229

967-881

