

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI  
(Other instructions  
verse side)

Form approved  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.

LC064118

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Eva E. Blinebry

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Langlie Mattix 7Rvrs, QN, GB.

11. SEC., T., R., W., OR BLK. AND  
SURVEY OR AREA

Sec. 35, T23S, R37E

12. COUNTY OR PARISH

Lea

13. STATE

N.Mex

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Plains Petroleum Operating Company

3. ADDRESS OF OPERATOR

415 W. Wall, Suite 1000, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980' FNL & 660' FWL, Unit Letter E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3257 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANE

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

X

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Please correct your records on the Blinebry #5 well. The API number obtained from the Oil Conservation Commission is

30-025-10962 (correct API No.)

(30-025-87064 - incorrect API No.)

Copy of OCD District I notification letter is attached.

RECEIVED  
FEB 18 11 13 AM '93  
OCD  
AREA

1993

18. I hereby certify that the foregoing is true and correct

SIGNED

*Bonnie Mustand*

TITLE Office Manager/Tech

DATE 02-17-93

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

RECEIVED

MAR 04 1996

CCO HODGES OFFICE



STATE OF NEW MEXICO  
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT  
OIL CONSERVATION DIVISION  
HOBBS DISTRICT OFFICE

February 15, 1993

POST OFFICE BOX 1980  
HOBBS, NEW MEXICO 88241-1980  
(505) 393-6161

BRUCE KING  
GOVERNOR

✓ Plains Petroleum Operating Company Attn: Bonnie Husband

415 West Wall, Suite 1000

Midland, TX 79701

RE: CORRECTING API NUMBERS

Gentlemen:

The Oil Conservation Division has started requiring API numbers for each well on operators C-115 report. As a result of this we have discovered incorrect API numbers on some federal wells. The API number on the federal well(s) listed below does not agree with the API records on file with the Oil Conservation Division office.


LEASE NAME, #, LOCATION	INCORRECT API #	CORRECT API #
-------------------------	-----------------	---------------

Eva E. Blinebry #5-E, Sec.35,T23S,R37E (1980/N & 660/W)	30-025-87064	30-025-10962
--	--------------	--------------

We need you as the operator of the well to file a Federal Sundry Notice (Form 3160-5) to the appropriate BLM office stating the correct API # and requesting the API # be corrected in their records. You need to advise them this corrected number was obtained for the Oil Conservation Division. If there is any questions, please call the Oil Conservation Division, District I Hobbs, NM (505) 393-6161.

Yours very truly,

OIL CONSERVATION DIVISION

  
Jerry Sexton  
District I, Supervisor

JS:dp  
CC: BLM, Santa Fe, well file



RECEIVED FEB 17 1993

RECEIVED

MAR 04 1993

ODD HORSES OFFICE