

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-064118

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

E. C. Hill 'B' Federal

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Teague (Blinbry)

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

Sec 35, T23S, R37E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Plains Petroleum Operating Company

3. ADDRESS OF OPERATOR

415 W. Wall, Suite 1000, Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit ~~X~~, Sec 35, T23S, R37E

E 1980/N + 810/W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3267' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANE

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

(Other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

09-21-92

Unset pump. POOH w/rods, pump. ND wellhead. Release TAC. PU & RIH w/tbg. Tag fill @ 5775' (15' fill). Pull tbg to landing SN @ 5422'. EOT @ 5456'. Set TAC @ 5233' w/16000# tension. NU wellhead. RU pump truck. Load tbg w/21 BPW. PSI tbg to 500#. Held OK. Release PSI. PU & RIH w/2" x 1-1/2" x 16' pump, (10) 7/8" x 25' plain steel rods, (137) 3/4" x 25' plain steel rods, (69) 7/8" x 25' plain steel rods, 7/8" x 4' x 4' x 4' x 4' pony rods, 1-1/4" x 22' polished steel rod. Seated & spaced pump. Hung on. Load tbg w/19 BPW. Start unit & PSI tbg to 400#. Open to flow line. Pumping to battery on 76" stroke @ 6 SPM.

18. I hereby certify that the foregoing is true and correct.

SIGNED

Bonnie Husband

TITLE Office Mgr/Tech

DATE

10-6-92

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side