

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER
2. NAME OF OPERATOR Amerada Petroleum Corporation
3. ADDRESS OF OPERATOR P.O. Box 668 - Hobbs, New Mexico
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FWL of Sec. 3
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3004' DF

5. LEASE DESIGNATION AND SERIAL NO. 030176-B Las Cruces
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME C.C. Cagle "C"
9. WELL NO. 3
10. FIELD AND POOL, OR WILDCAT Crosby Devonian
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3, T-26S, R-37E.
12. COUNTY OR PARISH Lee
13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) Temp. Abandon	
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*			

Ran casing cutters and cut 5-1/2" casing at 6010'. Recovered 144 jts. 5-1/2" OD casing. Ran 196 jts. 2-3/8" tubing set open ended at 6057'. Pumped 10 bbls. fresh water down tubing. Spotted 30 sack cement plug in top of 5-1/2" casing from 5991' to 6057'. Flushed with 23 bbls. salt gel mud. Reset tubing open ended at 5702'. Spotted 30 sack cement plug in base 8-5/8" casing from 3600' to 3703'. Filled 8-5/8" casing from surface to 3600' with salt gel mud. Finished pulling and laying down tubing. Installed well head and master valve. Temporarily abandoned pending possible future remedial work.

18. I hereby certify that the foregoing is true and correct

SIGNED L. C. Cagle, Jr.TITLE District SuperintendentDATE January 18, 1965

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

ACTING DISTRICT SUPERINTENDENT

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.