Form 3160-5 (November 1994)

UNILLD STATES

N.M. Oil Tins.	. Division
P.O. Box 1980	* 13 . 369#1
Hobbs, NM 882	<u> </u>

14	
	FORM APPROVED
	OMB No. 1004-0135
	Expires July 31, 1996

DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** 5. Lease Serial No. LC-054668 **SUNDRY NOTICES AND REPORTS ON WELLS** Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other Instructions on reverse side 8920003820 Type of Well Oil Well 🔯 Gas Well 🚨 Other Well Name and No. **RHODES FEDERAL UNIT #43** Name of Operator
Gruy Petroleum Management Co. 9. API Well No. 30-025-11949 3b. Phone No. (include area code) 3a. Address P. O. Box 140907 Irving, TX 75014-0907 972-401-3111 10. Field and Pool, or Exploratory Area Rhodes-Yates-7 Rivers Gas Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 2310' FSL & 99FWL Sec. 4-26S-37E Lea Co., NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Deepen Production (Start/Resume) ☐ Water Shut-Off X Acidize Notice of Intent Well Integrity Fracture Treat Reclamation Alter Casing Subsequent Report Other **New Construction** Recomplete Casing Repair Plug and Abandon Temporarily Abandon Change Plans ☐ Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) MIRU NDWH NUBOP. Tag CIBP @ 3150' KB. 03/05/98 MIRU pump truck, pumped 20 bbls 2% KCL wtr, POOH w/ tbg. Log from 3150' PBTD to 2150' 03/06/98 Perf'd 2680' - 2923', 1 jspf (114 holes). PU & RIH w/ bailer to dump 2 sx cement on CIBP. Acidize well w/ 2,200 gals 15% HCL. 03/09/98 CO2 Foam Frac well w/ 50Q CO2 foam & 77,200 lbs 16/30 Brady sand. 03/10/98 ACCEPTED FOR RECORD PETER W. CHESTER Set tbg @ 2915'. Well flowing on test. 03/11/98 SI WO pipeline connection. 03/12/98 BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE ARE 14. I hereby certify that the foregoing is true and correct Title Name (Printed/Typed) Manager Operations Administration Zeno Farris Date Signature eus Fo July 14, 1998 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date Title Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

01 30 A F1 30 829