

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN OR
OTHER INSTANT
FORM 1000

DATE

Form approved
BUREAU OF LANDS
LEASE REGISTRATION AND SERIAL NO.

LC-054658

IF INDIAN, AGENT'S OR TRIBE NAME

11 '66

SUNDRY NOTICES AND REPORTS ON WELLS

(Check whether Form for notice to drill or to deepen or plug back to a different reservoir.
(See "REGISTRATION FOR PERMIT" for such proposals.)

1. NAME OF WELL ☒ OTHER

2. NAME OF OPERATOR

AMERICAN PETROLEUM CORPORATION

3. LOCATION (Show location clearly and in accordance with any State requirements.)

Sec 66, Hobbs, New Mexico

4. UNIT AGREEMENT NAME

5. FARM OR LEASE NAME

FERNWORTH "C" FEDERAL

6. WELL NO.

5

7. THIRD AND FOUR, OR WILDCAT

DEVONIAN GRASS

8. LOCATION, TO, BY, OR DATE, AND
SURVEY OR AREA

4-26-37 NMPM

11. COUNTY

12. ELEVATIONS (SHOW WHETHER BF, MT, OR, ETC.)

3008' R.D. 15.

13. COUNTY OR PARISH

14. STATE

LEO

N.M.

15. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

1. DRILL OR DEEPEN

2. ALTER CASING

3. MULTIPLE COMPLETE

4. ABANDON*

5. CHANGE PLANS

6. FILL OR ALTER CASING

7. MULTIPLE COMPLETE

8. ABANDON*

9. CHANGE PLANS

SUBSEQUENT REPORT OF:

10. WATER SHUT-OFF

11. FRACTURE TREATMENT

12. SHOOTING OR ACIDIZING

(Other)

13. REPAIRING WELL

14. ALTERING CASING

15. ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Abandonment Report and Log form.)

16. Description of all completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any operations. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to the operations.)

Well is no longer capable of producing from the Devonian and further workover or recompletion possibilities are not feasible. Plugging and abandonment proposed as follows:

Sept 25 24 cement plug from 3613-3400 (perfs 3618-3606)
Sept 4 pull 5 1/2" (from app 3300).

Cement plugs:

2004. In & out of 5 1/2" stub (app 6050-5950)

25 3/4. 5200-5130'

45 3/4. 4100-3850 (3 3/4" CSA 3815')

10 3/4. Surface w/ PTA marker noted.

Make final cleanup and restore ground to control.

TO 3370, 200-3640, 13 3/4" CSA 600; 5 3/4" CSA 3875, 2 1/2", 5 1/2" CSA 6250. TCA 6250'

17. I certify that the foregoing is true and correct

SIGNED

TITLE

DATE 9-16-66

(This space for Federal or State office use)

APPROVED BY
SIGNATURE OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

APPROVED

SEP 20 1966

A. R. BROWN
DISTRICT ENGINEER