Farnsworth C No. 1 Rhodes (Yates - 7-River) Field Lea County, New Mexico

Project Engineer: K. L. Midkiff

Office: (915) 686-5714 Residence: (915) 686-8650

- MIRU PU. Kill well with 10 bbl of treated 2% KCl water. Deliver ±2600' of 2 7/8" 6.5# N-80 workstring and ±500' of 2 3/8" 4.7# N-80 workstring to location. ND wellhead. NU BOP. POOH and stand back production tubing.
- 2. RIH with 3 3/8" mill tooth bit, ±500 of 2 3/8" tubing and 2545' of 2 7/8" tubing. Clean out hole to bottom of liner at 3045' with foam. POOH.
- 3. RIH with 5 1/2" 17# treating packer on 2 7/8" workstring to ±2550'. Load annulus and set packer. MIRU stimulation company. NU surface lines and test to 7000 psi.
- 4. Break down current perforations with 1000 gallons of 7 1/2% NEFe HC1 acid. Pump at 4 BPM down tubing. Displace with treated 2% KC1 water. Space out 83 7/8" RCNBS (Sp. Gr. = 1.1)

Treatment Rate	=	4 BPM
Anticipated Pressure	=	1500 psi
Maximum Pressure	=	3725 psi

Release packer and POOH.

- 5. RIH with 3 3/8" bit to PBTD to knock balls off. POOH. RIH with packer to ±2550'. Load annulus and set packer. Test stimulation lines.
- 6. Fracture stimulate Yates down tubing with 29000 gallons of 65 Quality N_2 foam and 80000 lbs 12/20 mesh Brady sand. Pump at 20 BPM surface rate. Hold 1000 psi on annulus during job.

Anticipated Treating Pressure	= 4300 psi
Maximum Treating Pressure	= See Chart
Treating Rate	= 20 BPM

Rat	e	(70% of casing rating) <u>Maximum Treating Pressure</u>
0	BPM	3725 psi
5	BPM	4250 psi
10	BPM	50 2 5 psi
15	BPM	5850 psi
20	BPM	6700 psi



.