

UNITED STATES
DEPARTMENT OF THE INTERIOR
895 OFFICE & C.
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instruction: a re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC-049439 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to complete plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Tidewater Oil Company	8. FARM OR LEASE NAME GO-G-D. Rings "B"
3. ADDRESS OF OPERATOR Box 242, Hobbs, New Mexico	9. WELL NO. 8
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FNL and 1650' FEL, Sec. 1, 26S, 37E	10. FIELD AND POOL, OR WILDCAT Justin Drinkard
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3043 DF
	12. COUNTY, STATE Lea N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

This dual oil well is completed in the Drinkard and Blinbry zones in 5-1/2" casing. Blinbry Perforations 5111-5402'. Tubb-Drinkard perforations 5769-5824'.

Pulled Blinbry tubing. Attempted to pull Tubb Drinkard tubing, but could not release from Baker Model D packer at 5550'. Ran McCullough free point, tubing free at 5530'. Cut off at 5528'. Set cast iron bridge plug at 5525'. Dumped cement plug from 5525-5508'. FWD 5508'. Ran 2-3/8" SUE J-55 tubing and set at 5416'. Ran rods and pump for Blinbry zone.

18. I hereby certify that the foregoing is true and correct

Original Signed By
SIGNED C. L. WADE

TITLE Area Supt.

DATE 2-21-66

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE DATE

*See Instructions on Reverse Side

FEB 23 1966

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.