

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 062384

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Leopoldo Oil Company

RECEIVED

AUG 15 1951

ADMINISTRATION COMMISSION
HOBBS OFFICE

SUNDRY NOTICES AND REPORTS ON INVESTIGATION

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, New Mexico - May 10, 1950

Well No. 2 is located 660 ft. from N line and 660 ft. from E line of sec. 12

NE/4

(1/4 Sec. and Sec. No.)

T-26-S

(Twp.)

R-37-E

(Range)

NMPM

(Meridian)

Wildcat

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft. To be reported in a subsequent report.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is our intention to drill a well with rotary tools at the above location to a depth of approximately 12,500' unless commercial oil and/or gas production is encountered at a lesser depth. All casing points will be cemented in accordance with approved methods of the U.S.G.S. and all special requirements will be fully complied with.

The following casing program is contemplated:

Approx. 500' of 13-3/8" casing in 17-1/4" hole w/575 sx. cement.
Approx. 3750' of 9-5/8" casing in 17-1/4" hole w/1225 sx. cement.
Approx. 12500' of 5-1/2" casing in 7-7/8" hole w/200 sx. cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Stanolind Oil and Gas Company

Address Box "F"

Hobbs, New Mexico

By /s/ Ralph L. Hendrickson

Title Field Superintendent

1. The first part of the document discusses the importance of maintaining accurate records of all transactions and the role of the accounting department in ensuring the integrity of the financial statements.

2. It also highlights the need for regular audits and the importance of having a strong internal control system in place to prevent fraud and errors.

3. The second part of the document focuses on the importance of communication and collaboration between different departments, particularly between the accounting department and the sales and marketing teams.

4. It emphasizes the need for clear communication channels and the importance of providing timely and accurate information to all stakeholders.

5. The third part of the document discusses the importance of staying up-to-date with the latest accounting standards and regulations, and the role of the accounting department in ensuring compliance.

6. It also highlights the need for ongoing training and development for accounting staff to ensure they have the necessary skills and knowledge to perform their duties effectively.

7. The fourth part of the document focuses on the importance of maintaining a strong relationship with the external auditors and the role of the accounting department in preparing for the audit.

8. It emphasizes the need for transparency and openness in the audit process and the importance of providing all necessary documentation and information to the auditors.

9. The fifth part of the document discusses the importance of maintaining accurate records of all transactions and the role of the accounting department in ensuring the integrity of the financial statements.

10. It also highlights the need for regular audits and the importance of having a strong internal control system in place to prevent fraud and errors.