

Las Cruces

(SUBMIT IN TRIPLICATE)

Land Office

UNITED STATES

Lease No. 062324

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 30, 1950

Well No. 4-N is located 660 ft. from ^N_S line and 1960 ft. from ^E_W line of sec. 13

Sec. 13 (N. Sec. and Sec. No.) 26S (Twp.) 27E (Range) N.M.P.M. (Meridian)

South Leonard Field (Fld) Lea (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

June 29, 1950:

292' of 10-3/4", 24.70% Casing cemented to surface with 100 sac.
Will drill plug July 1, 1950, at 5:00 P.M. and test for shut-off.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Leonard Oil Company

Address P.O. Box 372

Roswell, New Mexico

By *Emmott D. White*

Title vic resident