

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil & Gas
P.O. Box 1001
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. LC 0301400 030180-A
2. Name of Operator SOUTHWEST ROYALTIES, INC.	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P.O. BOX 11390 MIDLAND, TX 79702 1 800 433 7945	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SEC. 18 T26S R37E 1650 FSL & 990 FWL LTR L	8. Well Name and No. FARNSWORTH A FEDERAL #6
	9. API Well No. 30 025 11998
	10. Field and Pool, or Exploratory Area SCARBOROUGH YATES 7 RIVERS
	11. County or Parish, State LEA COUNTY, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

RU PLUGGING COMPANY & ABANDON WELL AS FOLLOWS:

- 1) SET CIBP @ $\pm 2750'$ & CAP W/35' OF CMT.
- 2) LOAD CSG W/9.5 ppg OR GREATER MUD.
- 3) SPOT 15 SX PLUG FROM $\pm 2500'$ - 2644'.
- 4) PERF CSG @ $\pm 1230'$.
- 5) SQZ CMT LEAVING 35 SX INSIDE CASING & 35 SX OUTSIDE CSG.
- 6) PERF CSG @ 300'. SQZ CMT LEAVING 10 SX INSIDE THE CSG & 10 SX OUTSIDE THE CSG.
- 7) SPOT CMT FROM 3' - 30'.
- 8) WELD PLATE ON STUB. INSTALL P&A MARKER.
- 9) CLOSE CELLAR & RESTORE LOCATION.

**SEE ATTACHED FOR
CONDITIONS OF APPROVAL**

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title AREA SUPERVISOR

Date 06/22/99

(This space for Federal or State office use)

Approved by
Conditions of approval, if any:

Title

PETROLEUM ENGINEER

Date

JUL 08 1999

(ORIG. SGD.) LES BABYAK

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side