

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. LC0301 80 A
2. Name of Operator Southwest Royalties, Inc.	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P.O. Box 11390; Midland, Texas 79702	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980 FNL and 1980 FWL; Sec. 18, T26S, R37E	8. Well Name and No. Farnsworth A #5
	9. API Well No. 30 025 12002
	10. Field and Pool, or Exploratory Area Scarborough (Yates/7River)
	11. County or Parish, State Lea County, New Mexico

12. **CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other _____	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-30-98 - Notified Steve Caffey w/ BLM. Tagged CIBP @ 2834'. Circulated hole w/ mud and pumped 50 sx C cmt 2834-2520'. PUH to 1650' and pumped 35 sx C cmt. WOC and will tag on 7-1-98.

7-01-98 - Contacted Steve Caffey w/ BLM. Tagged plug @ 1433'. Perforated 7" csg w/ 4 shots @ 510'. Set packer and squeezed 240 sx C cmt out perfs, circulated to surface in 5-1/2". Tied onto 10-3/4" x 7" and squeezed 30 sx C cmt to surface. RD.

7-08-98 - Cut off wellhead and capped well. Backfilled pit, cleaned location and installed dry hole marker.

14. I hereby certify that the foregoing is true and correct

Signed <u>James Blow</u>	Title <u>AREA SUPERVISOR</u>	Date <u>7-10-98</u>
(This space for Federal or State office use)		
Approved <u>(ORIG. SGD.) GARY GOURLEY</u>	Title <u>PETROLEUM ENGINEER</u>	Date <u>JUL 14 1998</u>
Conditions of approval, if any:		

RECEIVED
FBI - NEW YORK
JUL 11 1962

JUL 13 1962

RECEIVED

7-13-62