

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.I. PL CONS. COMMISSION  
P.O. BOX 1980  
RECHOBOTTS, NEW MEXICO 88240

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

JUL 20 10 30 AM '94

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC-030168-A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Eaves A #6

9. API Well No.

30-025-12005

10. Field and Pool, or Exploratory Area

Scarborough, Yates - 7 Rivers

11. County or Parish, State

Lea Co., NM

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Hal J. Rasmussen Operating, Inc.

3. Address and Telephone No.

310 W. Wall, Ste. 906, Midland, TX 79701 915-687-1664

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL + 660' FWL, Unit Letter D  
Sec. 19, T26S, R37E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment  
☒ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well is currently SI.  
POOH with tbg and submersible pump.  
RIH with bit and scraper to 3200'. POOH.  
RIH with pkr and set at 3157'. Acidize  
RIH with pkr + RBP, set REP at 3157'.  
pkr at 2950'. Acidize.  
RIH with tubing and submersible pump and test.  
Place well on production

14. I hereby certify that the foregoing is true and correct

Signed

Lisa Angeltstein

Title

Engineering Tech

Date

7/14/94

(This space for (Orig. SGD.)

JOE G. LARA

Approved by

Conditions of approval, if any:

Title

PETROLEUM ENGINEER

Date

8/12/94

RECEIVED

AUG 14 1944

OFFICE