

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

MLI 538

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL CO., INC.	8. Farm or Lease Name South Leonard Unit Tr. 3
3. Address of Operator P.O. Box 1069 - Hobbs, New Mexico 88240	9. Well No. 6
4. Location of Well UNIT LETTER N , 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 23 TOWNSHIP 26-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat So. Leonard Queen
15. Elevation (Show whether DF, RT, GR, etc.) 2988'	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled rods and tubing. Cleaned out to TD. Ran 3" frac tbg and packer to 3150'. Logged to 3482'
2. Fraced w/20,000 gal My-T-Frac / 35,400# 16/20 sand in 2 stages.
3. Pulled frac tubing and packer. Ran 110 jts 2" tbg w/SW @ 3400'.
4. Ran pump and rods. Recovered load and placed on production.

Work completed 2-7-71

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lloyd Wright TITLE Area Superintendent DATE 4-5-74

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY: