

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fed ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection well	7. Unit Agreement Name South Leonard Unit
2. Name of Operator Texas Pacific Oil Company	8. Farm or Lease Name Tract 4
3. Address of Operator Post Office Box 1069 - Hobbs, New Mexico 88240	9. Well No. 16
4. Location of Well UNIT LETTER N 900 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 24 TOWNSHIP 26-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat So Leonard Queen
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER Acidize <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Upon approval, we proceeded to convert well to injection well for waterflood as follows:

- 1 Moved in, rigged up. Pulled rods & tbg Cleaned out to 3480'
- 2 Logged well Ran tbg & Packer
- 3 Spotted 300 gal 15% NE acid in open-hole Set pkr @ 3210'
- 4 Acidized open-hole w/1,500 gal NE acid Swabbed back load
- 5 Pulled tbg & pkr Ran 103 jts 2-3/8" tbg & packer to 3215'
- 6 Connected up well head according to standard wellhead injection diagram

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by

SIGNED Sheldon Ward TITLE Area Superintendent DATE 3-19-69
APPROVED BY [Signature] TITLE [Signature] DATE MAR 24 1969
CONDITIONS OF APPROVAL, IF ANY: